



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0925/2020/NS
DATE	:	27-Nov-20
WIP	:	59299

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR NOH BIN SALLEH
ADDRESS	:	56 BUKIT BATOK STREET 31 #06-17 SINGAPORE 659445
TELEPHONE	:	HP +65 97397171
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070113511
VEHICLE NO	:	SLB 1989 M
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR	:	4/8/2020
ENGINE NO	:	CVK 082853
CHASSIS NO	:	WAUZZZF41KN014147
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	26-Nov-20
PLACE OF ACCIDENT	:	BUKIT BATOK CENTRAL ABD BUKIT BATOK AVE 1 JUNCTION



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 1989 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00 ✓	
1			
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ?	
	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00 ✓ SSS	
3			
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00 ✓ SSS	
	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
5			
TOTAL LABOUR CHARGES		: \$ 4,922.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1989 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Redd</i>		\$	2,171.00	✓
2	FRONT BUMPER FIXING PARTS <i>neu</i>		\$	580.00	✗
3	FRONT BUMPER SECURING STRIP <i>?</i>		\$	35.00	?
4	FRONT BUMPER GRILLE - CENTRE <i>neu</i>		\$	194.00	✗
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>		\$	208.00	✗
6	FRONT BUMPER AIR GUIDE - RH <i>neu</i>		\$	62.00	✗
7	RADIATOR GRILLE <i>Cracked</i>		\$	1,317.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>neu</i>		\$	134.00	✗
9	FRONT BUMPER CARRIER <i>?</i> bent		\$	795.00	✓
10	FRONT BUMPER FOAM FILLER PIECE <i>?</i> cracked		\$	123.00	✓
11	FRONT BUMPER GUIDE SECTION - RH <i>neu</i>		\$	37.00	✗
12	FRONT BUMPER TOP COVER <i>neu</i>		\$	126.00	✗
13	CAUTION SIGN STICKER <i>neu</i>	NEC	\$	14.00	✗
14	AIRCON STICKER <i>neu</i>	NEC	\$	8.00	✗
15	LOCK CARRIER BRACKET <i>?</i> cracked		\$	136.00	✓
16	LOCK CARRIER BRACKET SUPPORT - LH/RH <i>?</i>	2	\$	56.00	?
17	HORN - RH LOW TONE <i>neu</i>		\$	124.00	✗
18	SPRING SHACKLE - RH <i>neu</i>		\$	29.00	✗
19	FRONT PARKING AID SENSOR - INNER/OUTER <i>?</i>	2	\$	484.00	✗
20	FRONT PARKING AID SEAL RING <i>neu</i>	4	\$	14.00	✗
SUB TOTAL SPARE PARTS			\$	6,647.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1989 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER - RH		\$	758.00	X
22	FRONT FENDER ATTACHMENT PARTS		\$	200.00	X
23	FRONT FENDER CLOSING ELEMENT - RH		\$	49.00	X
24	FRONT FENDER BRACKET - RH		\$	35.00	X
25	DEFORMATION ELEMENT BRACKET - RH		\$	49.00	X
26	WHEEL HOUSING LINER - RH		\$	239.00	X
27	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	230.00	X
28	WHEEL SPOILER - RH		\$	73.00	X
29	WHEEL SPOILER TRIM - RH		\$	36.00	X
30	STONE CHIP GUARD - RH		\$	50.00	X
31	TOP FENDER LEDGE COVER - UPPER		\$	31.00	X
32	TOP FENDER LEDGE COVER - LOWER		\$	23.00	X
33	LED HEADLIGHT - RH		\$	7,693.00	X
34	LIFT CYLINDER - RH		\$	208.00	?
35	LIFT CYLINDER CORRUGATED PIPE	nn	\$	92.00	X
36	RADIATOR AIR GUIDE - OUTER	nn	\$	28.00	X
37	RADIATOR AIR GUIDE - INNER	damaged	\$	12.00	X ✓
38	RADIATOR AIR GUIDE - UPPER	nn	\$	16.00	X
39	FRONT NO PLATE	S/N	\$	60.00	✓
40	SUNDRIES		\$	250.00	?
TOTAL SPARE PARTS			:	\$	16,779.00
TOTAL LABOUR CHARGES			:	\$	4,922.00
GRAND TOTAL			:	\$	21,701.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

*Admin by
30/11/20*

Not Authorised, 03 days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Acknowledged by Repairer Signature: Date:
---	---

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT