

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0925/2020/NS
DATE : 27-Nov-20
WIP : 59299

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

6 days - ok - Jy - 25 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR NOH BIN SALLEH
ADDRESS : 56 BUKIT BATOK STREET 31
#06-17
SINGAPORE 659445
TELEPHONE : HP +65 97397171
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070113511
VEHICLE NO : **SLB 1989 M**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 04/08/2020
ENGINE NO : CVK 082853
CHASSIS NO : WAUZZZF41KN014147
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Nov-20
PLACE OF ACCIDENT : BUKIT BATOK CENTRAL ABD BUKIT
BATOK AVE 1 JUNCTION

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 1989 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	280.00	\$	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$	550.00
	<i>SUPPLEMENTARY</i>			\$	780.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 4,922.00	\$	2,302.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1989 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,171.00	\$ 1,736.80
2	FRONT BUMPER FIXING PARTS		\$ 580.00	
3	FRONT BUMPER SECURING STRIP		\$ 35.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 208.00	
6	FRONT BUMPER AIR GUIDE - RH		\$ 62.00	
7	RADIATOR GRILLE		\$ 1,317.00	\$ 1,053.60
8	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 134.00	
9	FRONT BUMPER CARRIER		\$ 795.00	\$ 635.60
10	FRONT BUMPER FOAM FILLER PIECE		\$ 123.00	\$ 98.40
11	FRONT BUMPER GUIDE SECTION - RH		\$ 37.00	
12	FRONT BUMPER TOP COVER		\$ 126.00	
13	CAUTION SIGN STICKER	NEC	\$ 14.00	
14	AIRCON STICKER	NEC	\$ 8.00	
15	LOCK CARRIER BRACKET		\$ 136.00	\$ 108.40
16	LOCK CARRIER BRACKET SUPPORT - LH/RH	2	\$ 56.00	
17	HORN - RH LOW TONE		\$ 124.00	
18	SPRING SHACKLE - RH		\$ 29.00	
19	FRONT PARKING AID SENSOR - INNER/OUTER	2	\$ 484.00	
20	FRONT PARKING AID SEAL RING	4	\$ 14.00	
SUB TOTAL SPARE PARTS		:	\$ 6,647.00	\$ 3,632.80

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1989 M

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
	<i>c/f</i>		\$	3,632.80
21	FRONT FENDER - RH	\$	758.00	
22	FRONT FENDER ATTACHMENT PARTS	\$	200.00	
23	FRONT FENDER CLOSING ELEMENT - RH	\$	49.00	
24	FRONT FENDER BRACKET - RH	\$	35.00	
25	DEFORMATION ELEMENT BRACKET - RH	\$	49.00	
26	WHEEL HOUSING LINER- RH	\$	239.00	
27	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	230.00	
28	WHEEL SPOILER - RH	\$	73.00	
29	WHEEL SPOILER TRIM - RH	\$	36.00	
30	STONE CHIP GUARD - RH	\$	50.00	
31	TOP FENDER LEDGE COVER - UPPER	\$	31.00	
32	TOP FENDER LEDGE COVER - LOWER	\$	23.00	
33	LED HEADLIGHT - RH	\$	7,693.00	
34	LIFT CYLINDER - RH	\$	208.00	
35	LIFT CYLINDER CORRUGATED PIPE	\$	92.00	
36	RADIATOR AIR GUIDE - OUTER	\$	28.00	
37	RADIATOR AIR GUIDE - INNER	\$	12.00	\$ 9.36
38	RADIATOR AIR GUIDE - UPPER	\$	16.00	
39	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
40	SUPPLEMENTARY	\$	1,209.00	\$ 342.96
41	SUNDRIES	\$	250.00	\$ 1.12
TOTAL SPARE PARTS		:	\$ 17,988.00	\$ 4,046.24
TOTAL LABOUR CHARGES		:	\$ 4,922.00	\$ 2,302.00
GRAND TOTAL		:	\$ 22,910.00	\$ 6,348.24

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

**Supplementary Estimate 2**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.**Date****Service Advisor****Pages****Regn No****Model No**

PA/OD/0925/2020/NS

22-Dec-20

GEORGE

1 of 1

SLB 1989 M

A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>LABOUR</u>			
1	To dislodge and reinstall front lock carrier to facilitate the renewal of front rhs bumper reinforcement bracket	s/n \$ 780.00	\$ 780.00
<u>PARTS</u>			
1	FRONT BUMPER REINFORCEMENT BRACKET-RH	\$ 225.00	\$ 180.00
2	BONNET IMPACT PROTECTION - CENTRE	\$ 27.00	\$ 21.52
3	RADIATOR COOLANT	\$ 177.00	\$ 141.44
GRAND TOTAL		\$ 1,209.00	\$ 1,122.96

For Premium Automobiles Pte Ltd

Authorised Signature

