

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0932/2020/NS
DATE : 30-Nov-20
WIP : 59378

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : GBH 5392 U

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LOH TENG JOO(LU TINGYU)
ADDRESS : BLK 247 PASIR RIS STREET 21
#09-145
SINGAPORE 510247
TELEPHONE : HP +65 98511754
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00755445
VEHICLE NO : **SLW 1265 H**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 30/1/2018
ENGINE NO : CVK 049078
CHASSIS NO : WAUZZZF49JA062713
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Nov-20
PLACE OF ACCIDENT : PASIR RIS DRIVE 8

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 1265 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	
3	TO RESPRAY REAR BUMPER.	\$ 900.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 1265 H

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER		\$	2,181.00	
2	REAR BUMPER FIXING PARTS		\$	72.00	
3	REAR BUMPER SECURING STRIP		\$	220.00	
4	REAR BUMPER SPOILER		\$	246.00	
5	REAR LIGHT REFLECTOR - LH/RH	2	\$	82.00	
6	REAR BUMPER CARRIER		\$	886.00	
7	REAR BUMPER CARRIER SEAL	2	\$	28.00	
8	REAR BUMPER GUIDE SECTION - LH/RH	2	\$	44.00	
9	REAR PARKING AID SENSOR - INNER/OUTER	2	\$	484.00	
10	REAR PARKING AID SEAL RING	4	\$	14.00	
11	SUNDRIES		\$	200.00	
TOTAL SPARE PARTS		:	\$	4,457.00	
TOTAL LABOUR CHARGES		:	\$	2,502.00	
GRAND TOTAL		:	\$	6,959.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT