



Address : 1 Kaki Bukit Avenue 6 #02-22/20 Autobay
S(417883)
Reg no 201828067M

VEHICLE REPAIR ESTIMATE

Insurance Company: ECICS INSURANCE

Address: NO 10, EUNOS ROAD 8 ,#09-04A
SINGAPORE POST CENTRE ,S(408600)

Telephone: 63374779 Fax: Email:claims@ecics.com.sg

Make/ Model : BMW 523I Date: 09.12.2020

Chassis No : WBAFP320X0C863761 Vehicle No: SDP24A

Date/Time of Accide 27.11.2020/1645 Date of Reg : 16.02.2011

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	BOOTLID <i>Rejs</i>	1	\$ 1,652.30	\$ <i>x</i> 1,652.30
2	BOOTLID LOGO <i>new</i>	1	\$ 98.50	\$ <i>✓</i> 98.50
3	BOOTLID INNER LOCK <i>new</i>	1	\$ 425.40	\$ <i>x</i> 425.40
4	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 198.30	\$ <i>x</i> 198.30
5	BOOTLID LAMPS <i>new</i>	2	\$ 562.30	\$ <i>+</i> 1,124.60
6	BOOTLID LAMPS INNER SEALER <i>new</i>	2	\$ 40.00	\$ <i>+</i> 80.00
7	TAILAMPS <i>new</i>	2	\$ 645.80	\$ <i>+</i> 1,291.60
8	TAILAMPS INNER SEALER <i>new</i>	2	\$ 40.00	\$ <i>+</i> 80.00
9	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 185.60	\$ <i>-</i> 371.20
10	REAR BUMPER CENTRE RETAINER <i>new</i>	1	\$ 205.80	\$ <i>✓</i> 205.80
11	REVERSE SENSOR <i>Damaged 2 pieces</i>	4	\$ 285.30	\$ <i>570.60</i> 1,141.20
12	REVERSE SENSOR HOLDERS <i>new</i>	4	\$ 68.90	\$ <i>x</i> 275.60
13	REAR BUMPER REINFORCEMENT <i>Damaged</i>	1	\$ 697.50	\$ <i>✓</i> 697.50
14	REAR BUMPER REFLECTORS <i>new</i>	2	\$ 98.60	\$ <i>+</i> 197.20
15	END PANEL <i>Rejs</i>	1	\$ 852.30	\$ <i>+</i> 852.30
16	END PANEL TOP GARNISH <i>new</i>	1	\$ 265.30	\$ <i>+</i> 265.30
17	REAR HEAT SHIELD <i>new</i>	2	\$ 345.20	\$ <i>+</i> 690.40
18	REAR SILENCER BOX <i>new</i>	2	\$ 1,345.80	\$ <i>+</i> 2,691.60
19	REAR EXHAUST MOUNTING <i>new</i>	2	\$ 65.30	\$ <i>+</i> 130.60
20	REAR EXHAUST GASKET <i>new</i>	1	\$ 85.90	\$ <i>+</i> 85.90

Total List Price Cost

PARTS DISCOUNT 10% \$ 11,299.77

1943

1748-70

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1SET	\$ 50.00	\$ + 50.00
2	REAR BMW M PERFORMANCE BUMPER <i>new</i>	1	\$ 2,800.00	\$ 1800 2,800.00
3	REAR BMW LOWER DIFFUSER <i>new</i>	1	\$ 1,550.00	\$ 1200 1,550.00
4	TAILAMPS CLIPS <i>new</i>	2SET	\$ 30.00	\$ + 60.00
5	REAR BUMPER CLIPS <i>new</i>	1SET	\$ 30.00	\$ + 30.00
6	END PANEL SEALANT <i>new</i>	1SET	\$ 280.00	\$ + 280.00
7	END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ + 30.00
Total Special Nett Items				\$ 4,800.00

3030

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,200.00
<i>400</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,000.00
<i>500</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 40 200.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 60 150.00
TO REMOVE / REFIT / REPLACE REAR SILENCER BOX	\$ X 150.00
WIRING CHECK, TO REMOVE AND ADJUST TAILAMPS	\$ + 150.00
TO REMOVE AND REPLACE TAILGATE MECHANISM	\$ X 150.00
Total Others Cost	\$ 800.00
GRAND TOTAL	
	\$ 21,099.77

1000

Adrian G
H/s 10/12/20

OA Days

Total: 5778.70
H/s: 4-6K.

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allan@casgarage.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____