

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
INDIA INTERNATIONAL INSURANCE PL			Ref : CS3/III19022379/E	td3e2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date: 02-12-2020 Code: III2			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBH 2831P	Veh. Inspected	FBC 2260M	
	Policy No.	AR/50644/20/iii/pd	Coverage (\$)	0.00	
	Claim No.	MFL2019D0001639	Excess (\$)	0.00	
	Assign From	ANGELINE RAJOO	Assign Date	24/11/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CBF150	c.c	149	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	LALKC11A673006491	Colour	BLUE	
	Odometer	66308	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	80/80-18	NYLON	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90-18	NYLON	5 mm	
	L/H Rear Tyre			mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/12/2019	Inspection Date	20/12/2019	
	Survey held at CHEK KONG MOTOR				
		387B YEW YEE INDUSTRIAL ESTATE WOODLANDS ROAD SINGAPORE 677948			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				