

SGF6686M.
Honda Vezel
RU11107262

TPA16.
Xiao Tong.

Rear Number Plate. Best	30(SN) ✓
Rear Number Plate Holder Behind	30(SN) ✓
Rear Bumper Deformed	459.40 ✓
Rear Bumper Clips. new	30(SN) ✓
Rear Bumper Side Holder x02 new	23.5 x 2 = 47. ✓
Rear Bumper Reflector x02 behind	141.1 x 2 = 282.20 ✓
Reverse Sensor Dented	280(SN) 200(SN)
Rear End Panel. Dented	585 ✓
Rear End Panel Top Garnish. Behind	98.40 ✓
Rear End Panel Top Garnish Clips. new	20(SN) ✓
Rear End Panel Sealant. new	60(SN) ✓
Rear End Panel Antenna Sensor new	90.80 +
Rear End Panel Buzzer. Dented	85.20 ✓
Taillamp x02 new	474.6 x 2 = 949.20 +
Taillamp Lower Apron x02 Repair	195 x 2 = 390 +

SGF6696M.

Tailgate	Distorted	1100 ✓
Tailgate Lock	Dem'd	182.50 ✓
Tailgate Weatherstripe.	lt	165.40 ✓
Tailgate Reflector x02	NH m	$413.2 \times 2 = 826.40$ ✕
Tailgate Inner Trim Board	ould	285.60 -
Tailgate Inner Trim Board clips.	m	30(SN) ✓
Tailgate Outer Garnish.	NH m	395.20 ✕
Tailgate Glass Moulding	per	120 ✓
Tailgate Glass Sealant.		60(SN) ✓
Honda Logo.	NH m	30.40 ✕
Vezel Emblem.	Nec	45.90 ✓
Spere Tyre Panel Top Cover.	NH m	306.20 ✕
Spere Tyre Panel Under cover.	Behind	225.10 ✕
Spere Tyre Panel Under Cover Clips.	per	30(SN) ✓
Rees Fender Inner Trim Board x02	NH	$305.2 \times 2 = 610.40$ ✕
Rees Fender Inner Trim Board clips.		60(SN) ✕

SGF6696M.

Panel Beating

Spray Painting

Wiring.

To remove reverse sensor

To remove rear camera.

To remove video recorder.

To remove upholstery.

To transfer tailgate fittings

To remove tailgate glass.

To spray tuff coat.

~~1400~~ 8w

~~1200~~ 8w

~~50~~ 30

~~100~~ 50

~~100~~ 50

~~100~~ 50

~~150~~ 60

~~150~~ 80

~~180~~ 120

~~150~~ 60.

list: 3681.70

rem 20%: 2945.36

S.N: 490

Labour: 2100

total: 5535.36

h/s: A.HK.

06 Pmp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: