

[illegible]



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. **SGJ7710C HYUNDAI TUCSON 2.0A**

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	600.00	200 250
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	200 400 200 510
3	To perform anti-rust treatment on affected areas	30.00	
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00 30 X 2	
5	To remove, re-fix/replace and focus headlamp beam	30.00	
Labour Total :		1120.00	
TOTAL (PARTS & LABOUR):		2069.80	

592.00
510.00
1102.00

20%
881.60

45.900

Pass
Hp 900/100 68

2 days

C/S

07/12/2020 @ 1050

Rey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: