

YIG (Lsuni)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 01.12.2020
Time: 13:37:21
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305436671
REGN NO : SH 8326R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 11.01.2017
DATE/TIME IN : 28.11.2020 08:20
ACCIDENT DATE : 27.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	de
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nei
0003 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	nei

SUB-TOTAL : 952.40 ✓

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30 510

SUB-TOTAL : 680.00

TOTAL : 1,632.40 1462.50

MVA NAME & SIGNATURE

DATE: 01/12/20

SURVEYOR NAME & SIGNATURE

DATE:

AUTHORISED : YES / NO

4/5 1150
2 days #

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphin 97495744
WP 1/12/20 2 4pm
2 days
4/5 Resurvey after repair
tanphin@lkkauto.com