

Lion City Rental Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 01/12/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLQ415E
CHASSIS NO : JTDKB3FU003560789
MAKE / MODEL : Toyota Pirus Hybrid 1.8
DATE OF ACCIDENT : 29/11/2020
YOUR INSURED VEHICLE NUMBER : SLX9957L
Mileage: 235866km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 F/R fender / CR4	1PC	\$ 933.10	\$ 933.10
2 F/R fender Hybrid emblem / Nec	1PC	\$ 52.30	\$ 52.30
3 F/R fender inner liner X SVC	1PC	\$ 194.30	\$ 194.30
4 Front bonnet / PP	1PC	\$ 938.40	\$ 938.40
5 Front bonnet insulator X SVC	1PC	\$ 393.30	\$ 393.30
6 F/R headlamp / CR4	1PC	\$ 2,530.10	\$ 2,530.10
7 F/R headlamp retainer / BR	1PC	\$ 33.20	\$ 33.20
8 Radiator grille / CR4	1PC	\$ 331.90	\$ 331.90
9 Front bumper reinforcement / PP	1PC	\$ 691.10	\$ 691.10
10 Front bumper energy absorber / CR4	1PC	\$ 69.80	\$ 69.80
11 Front bumper / CR4	1PC	\$ 495.50	\$ 495.50
12 Front bumper RH side bracket X SVC	1PC	\$ 56.80	\$ 56.80
13 Front bumper RH tow cover / CR4	1PC	\$ 28.10	\$ 28.10
15 F/R fog lamp / CR4	1PC	\$ 910.20	\$ 910.20
16 Waher tank / CR4	1PC	\$ 181.80	\$ 181.80
		LIST TOTAL S\$:	\$ 7,839.90
		25%DISCOUNT S\$:	\$ 1,959.98
			\$ 5,879.93

LABOUR CHARGES

- | | | |
|--|-------------|---------|
| 1 To labour charge for removing out F/R fender, front bumper to facilitate replacement of damaged parts and incude starightening support panel | \$ 1,200.00 | 800 |
| 2 To respray front bonnet, front bumper, F/R fender and support panel (Pearl Paint) | \$ 1,200.00 | 800 500 |
| 3 To check lighting system | \$ 80.00 | 30 |
| 4 Towing fee | \$ 50.00 | ✓ |

LABOUR TOTAL S\$: \$ 2,530.00
TOTAL S\$: \$ 8,409.93
7% GST \$ 588.69
GRAND TOTAL S\$: \$ 8,998.62

Repair dy - 4 days
LIS
After pun photo
Sun Pin (LH)
02/12/2020
TP without prejudice.