



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 8801T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	DENTED	1,782.20	1,782.20
1	BONNET LOGO	NECESSARY	72.80	72.80
1	HEADLAMP	CRACKED	2,652.40	2,652.40
1	FRONT BUMPER	CUT / TORN	1,240.00	1,240.00
1	FRONT BUMPER SENSOR	MALFUNCTION	192.50	192.50
1	FRONT BUMPER SPONGE	SERVICEABLE	92.50	-
1	FRONT BUMPER CENTRE SUPPORT	CRACKED	126.30	126.30
1	FRONT GRILLE	CRACKED	147.20	147.20
1	FRONT GRILLE BASE	CRACKED	228.00	228.00
1	FRONT GRILLE LOGO	CRACKED	146.20	146.20
1	FRONT GRILLE MOULDING RH - UPPER	NOT NECESSARY	78.60	-
1	FRONT GRILLE MOULDING RH - LOWER	NOT NECESSARY	74.20	-
1	RADIATOR TOP PANEL	DENTED	577.20	577.20
1	RADIATOR TOP PANEL GARNISH	TORN	146.25	146.25
1	FRONT FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-	-731.11
			7,556.35	6,579.94
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		900.00	500.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		700.00	500.00
	TO CARRY OUT BODY PANEL CAVITY TREATMENT.		150.00	40.00
	TO CHECK WIRING SYSTEM FOR PROPER FUNCTIONS.		100.00	30.00
	TO CARRY OUT DIAGNOSTIC TEST AND RESET SETTINGS WHERE NECESSARY.		250.00	150.00
			2,100.00	1,220.00
	<b>GRAND TOTAL</b>		<b>9,656.35</b>	<b>7,799.94</b>



RECOMMENDED COST OF REPAIRS			7,799.94
-----------------------------	--	--	----------

Report Ref No. CS3/LPC20008987/R1tf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.