



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S CLC MACHINERY PTE LTD

20 SENOKO DR

SINGAPORE 758207

Insured CLC MACHINERY PTE LTD

Policy DMCVSNW00068312000

ESTIMATE Bill

GST Reg. No: 19-9800107D

Date: 27/11/2020

Our Case Ref. SC20/11/140/4CM-TP

Accident Date 26/11/2020

Damaged Vehicle No: XE4261B

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					(SN)
1	LHS REAR MUDGUARD / BMC.	1 PC	\$620.00	-	\$620.00
<u>Labour Charges</u>					
1	LABOUR FOR LHS PORTION 640 ✓	1	\$1,920.00	-	\$1,920.00
2	LABOUR FOR SPRAY PAINTING 800 ✓	1	\$1,300.00	-	\$1,300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

part by part.
before paint photos.

2 Days.

Guo Qiang - 82880282

Guo Qiang@lkkauto.com

Sub Total

\$ 3,840.00

Authorised Signature