

SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133 **T** 65 6758 2222 **F** 65 6257 6931 **E** sales@scauto.com.sg scauto.com.sg

Co. Reg. No. 199800107D

M/S

CLC MACHINERY PTE LTD

20 SENOKO DR

SINGAPORE 758207

Insured

CLC MACHINERY PTE LTD

Policy

DMCVSNW00068312000

ESTIMATE Bill

GST Reg. No:

19-9800107D

Date:

27/11/2020

Our Case Ref.

SC20/11/140/4CM-TP

Accident Date

26/11/2020

Damaged Vehicle No: XE4261B					
S/no	Description	QTY	Price	Disc	Amount
1	Replaced Parts LHS REAR MUDGUARD / Buc.	1 PC	\$620.00	-	(SV) \$620.00
1 2	Labour Charges LABOUR FOR LHS PORTION 640. LABOUR FOR SPRAY PAINTING 800	pat h	\$1,920.00 \$1,300.00	-	\$1,920.00 \$1,300.00
		pat h before	part	- phy	tos.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

2 Days. Guo Quang -82880282 Guo Qiang @ Ikkanto.com

Sub Total

\$ 3,840.00

Authorised Signature