

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0359/20
DATE : 27-NOV-2020

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
S(039190)
TEL : 68046059
FAX : 62353354
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : CHEW CHOO HENG CATHERINE @ TAN BEE KHIM
ADDRESS : BLK 41A BEDOK RIA CRESCENT
#03-56
S(489929)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1900006595-01
VEHICLE NO : SMH2932B
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12273499J-E12S
CHASSIS NO : JN1TAAE12Z0982685
MILEAGE : 3840 KM
DATE IN : 27/11/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 26/11/2020

-9645 0084 elmer@tancho ng. com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH2932B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RR END PANEL & RR BUMPER RENEW TRUNKLID	1170.00	780 ✓
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	1000.00	500 ✓
3 ZZ/003	REMOVE AND INSTALL REAR WINDSCREEN GLASS	180.00	/ ✓
4 ZZ/004	REMOVE AND INSTALL REVERSE CAMERA	120.00	/ ✓
5 ZZ/005	REMOVE AND INSTALL RR COMBINATION LAMP	48.00	/ ✓
6 ZZ/006	REMOVE AND TRANSFER TRUNKLID MECHANISM	80.00	/ ✓
7 ZZ/007	RENEW REVERSE SENSOR	55.00	/ ✓
8 ZZ/008	SUPPLY REAR LICENSE PLATE		✓
TOTAL LABOUR CHARGES		2653.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH29328

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/NETT REMARKS
		NETT	LIST		
1 REAR LICENCE PLATE X <i>San</i>	RLP				60.00
2 FINISHER BACK DOOR NO PLATE X <i>San</i>	90810-3VA5B	243.90			
3 PLATE-LUGGAGE REAR GARNISH <i>set</i>	84992-3VA0A	68.80	✓		
4 WEATHER STRIP TAIL GATE <i>Tri</i>	90830-3VA0A	68.20	✓		
5 TAIL GATE LOCK <i>BT</i>	90502-1HMOA	128.40	✓		
6 TAIL GATE <i>buc</i>	K010M-3VAMA	1018.20	✓		
7 SUNDRIES <i>MCC</i>	NPN				50.00 <i>Ro</i> ✓
8 EMBLEM-BACK DOOR NISSAN <i>MCC</i>	90890-3VA0A	64.90	✓		
9 ORNAMENT-BACK DOOR NOTE <i>MCC</i>	90892-3VA0A	79.90	✓		
10 REAR W/SCREEN SEALANT <i>MCC</i>	SEALANT - 4				80.00 ✓
11 SENSOR-REVERSE ?	SENSOR	nn	X		250.00
SUB TOTAL	1428.4	1672.30	0.00		440.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		334.46	0.00		0.00
GRAND TOTAL	1142.72	1337.84	0.00		440.00 100
OVERALL TOTAL		1777.84			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

3005.72

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMH2932B

TOTAL LABOUR CHARGES	2653.00
TOTAL SPARE PARTS CHARGES	1777.84
GRAND TOTAL	4430.84 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

One Day 82880282

4 Days.

before paint photos.

02/12/2020.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: