

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

01-12-2020

OUR REF NO. SMG 3499G

SALEH BIN MOHAMAD
BLK 259 TAMPINES ST 21
#06-330
SINGAPORE 520259

ESTIMATE BILL FOR VEHICLE NO. SMQ 3499G MODEL : KIA CERATO

LIST ITEM :

1) BONNET		\$ 1,468.80	835
2) BONNET HINGE	2PCS @\$69.00	\$ 138.00	Rx
3) BONNET STOPPER (SMALL)	2PCS @\$18.00	\$ 36.00	? ant
4) BONNET STOPPER (MEDIUM)	2PCS @\$21.00	\$ 42.00	? x un
5) BONNET STOPPER (LARGE)	2PCS @\$25.00	\$ 50.00	? x un
6) BONNET INSULATOR		\$ 298.40	X un
7) BONNET INSULATOR CLIPS	12PCS @\$6.50	\$ 78.00	X un
8) BONNET LOCK		\$ 224.00	? ant
9) BONNET LOCK CABLE		\$ 89.00	X un
10) HEADLAMP	2PCS @\$1,642.00	\$ 3,284.00	X un
11) FRONT GRILLE CHROME (TOP)		\$ 112.00	ant
12) FRONT GRILLE CHROME (BOTTOM)		\$ 128.00	? ant
13) FRONT GRILLE BASE		\$ 393.60	? ang
14) FRONT LOWER GRILLE		\$ 417.60	X un
15) FRONT BUMPER LOGO		\$ 48.00	un
16) FRONT BUMPER		\$ 795.60	de - 689
17) FRONT BUMPER CLIPS	10PCS @\$6.50	\$ 65.00	un
18) FRONT BUMPER (LOWER)		\$ 459.20	? ang
19) FRONT BUMPER LOWER COVER		\$ 182.00	X un

20) FRONT BUMPER SIDE ATTACHEMENT

2PCS @\$38.00

21) FRONT BUMPER SPONGE

22) FRONT BUMPER REINFORCEMENT

23) OUTSIDE TEMPARATURE SENSOR

24) FRONT SUPPORT PANEL

25) SUPPORT PANEL TOP GARNISH

26) CONDENSOR

27) RADIATOR

LESS DISCOUNT - 10%

SPECIAL NETT ITEM

1) FRONT LICENCE PLATE EMBOSS WITH HOLDER

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM

2) TO APPLY UNDER SEALING ON AFFECTED AREAS

3) TO REMOVE/REFIX HEADLAMP ASSY, REALIGNMENT LIGHTING SYSTEM

4) TO REMOVE/REFIX AIR-CON CONDESOR, PIPING SYTEM & TOP UP GAS

5) TO REMOVE/REFIX RADIATOR ASSY & CONDUCT PRESSURE TEST

6) TO RESPRAY ON EFFECTED AREAS

7) TO REPLACE NEW PART, CUT, WELD, KNOCK ETC

\$ 76.00 x un
\$ 299.00 ? un 84
\$ 486.00 ? h
\$ 129.00 x un
\$ 971.00 x un
\$ 181.00 ? de
\$ 696.00 x un
\$ 689.00 x un 3740.00
\$ 11,836.20 3366.72
\$ 1,183.62
\$ 10,652.58

\$ 55.00 45
\$ 55.00
45

\$ 60.00 30

\$ 120.00 x un

\$ 240.00 x un

\$ 180.00 x un

\$ 180.00 x un

\$ 1,100.00 500

\$ 660.00 400

\$ 2,540.00

GRAND TOTAL: \$ 13,247.58

Taufik 97495749

WP 02/12/20 @ 1030

Lumpsum 3-4 days
Resurvey after repair

Taufik @ 11 hours on

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To identify damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supply items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: