



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2106560

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 20/09/2021
Reference CC6/CTI20013217/Drs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 1107U
Insured Veh. YP 2567M
Claim No. SNM20D204674/LKKDS
Policy No. DMCVSNA00035092000
Accident Date 27/11/2020
Inspection Date 02/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI20013217/Drs3q2 Date: 20/09/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 2567M	Veh. Inspected	SHA 1107U
Policy No.	DMCVSNA00035092000	Coverage (\$)	0.00
Claim No.	SNM20D204674/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	02/12/2020
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU097750	Colour	BLUE
Odometer	293311 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	5 mm
L/H Front Tyre	205/60 R16	HANKOOK	5 mm
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/11/2020	Inspection Date	02/12/2020
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1107U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER	DENTED	2,171.40	2,171.40
1	REAR WINDSCREEN MOULDING	NECESSARY	51.80	51.80
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	ROCKER PANEL OUTER GARNISH (LH)	NOT NECESSARY	732.80	-
1	BONNET	NOT NECESSARY	2,265.90	-
2	BONNET HINGE (LH/RH) @\$126.70	NOT NECESSARY	253.40	-
1	BONNET INSULATOR	NOT NECESSARY	202.50	-
10	BONNET INSULATOR CLIP	NOT NECESSARY	36.80	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	15.00	-
1	FRONT BUMPER COVER	BENT	1,052.20	1,052.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	588.40	-
2	FRONT BUMPER BRACKET (LH/RH) @\$49.20	NOT NECESSARY	98.40	-
1	FRONT BUMPER RETAINER MOUNTING	NOT NECESSARY	76.20	-
1	HEADLAMP SUPPORT PANEL ASSY	NOT NECESSARY	907.40	-
1	HEADLAMP (LH)	CUT / MTG BROKEN	2,776.00	1,388.00
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	NOT NECESSARY	637.00	-
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	174.90	-
1	FRONT DOOR MIRROR SIDE GARNISH	NOT NECESSARY	225.00	-
1	FRONT DOOR MIRROR (LH)	BROKEN	670.00	670.00
1	FRONT DOOR (LH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR HINGE UPPER (LH)	NOT NECESSARY	113.60	-
1	FRONT DOOR HINGE LOWER (LH)	NOT NECESSARY	125.70	-
1	FRONT WHEEL RIM (LH)	DISTORTED	650.60	325.30
1	KNUCKLE ARM (LH)	DISTORTED	595.90	552.00
1	FRONT WHEEL BEARING HUB ASSY (LH)	DAMAGED	673.20	540.50
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	1,104.00	529.30
1	FRONT SHOCK ABSORBER ASSY (LH)	DISTORTED	684.40	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	217.60	-

Report Ref No. CC6/CTI20013217/Drs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STG TIE ROD (LH)	NOT NECESSARY	186.40	-
1	STG TIE END (LH)	DISTORTED	125.20	125.20
1	STABILIZER BAR ASSY	NOT NECESSARY	463.70	-
1	STABILIZER BAR LINK (LH)	NOT NECESSARY	68.10	-
1	ABS SENSOR	NOT NECESSARY	217.90	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	2,061.60	-
1	RACK & PINION ASSY	NOT NECESSARY	1,820.00	-
1	REAR TYRE RIM (LH) (ADDITIONAL)	DISTORTED	650.60	325.30
1	REAR TYRE WHEEL CAP (ADDITIONAL)	CUT	214.20	107.10
1	REAR WHEEL BEARING ING & HUB (ADDITIONAL)	DAMAGED	724.00	362.00
1	REAR TRAILING ARM (LH) (ADDITIONAL)	DISTORTED	384.00	192.00
1	REAR ASSIST (LH) (ADDITIONAL)	DISTORTED	219.40	145.70
1	REAR SHOCK ABSORBER (LH) (ADDITIONAL)	DISTORTED	683.70	276.30
1	REAR UPPER ARM (LH) (ADDITIONAL)	BENT	335.75	335.75
1	REAR LOWER ARM (LH) (ADDITIONAL)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH) (ADDITIONAL)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-6,280.09	-3,083.05
			25,120.36	12,332.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			417.00	201.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,600.00	900.00
	SPRAY PAINTING CHARGE.		1,400.00	900.00
	WIRING CHARGE.		160.00	30.00
	TUFF KOTE.		180.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS .		120.00	80.00
	TRANSFER OF DOOR MECHANISM FRONT .		80.00	60.00

Report Ref No. CC6/CTI20013217/Drs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER OF DOOR MECHANISM REAR .		80.00	60.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	RE-SET FRT ABS SYSTEM. }		200.00	150.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.}		550.00	-
			4,970.00	2,430.00
	GRAND TOTAL		30,507.36	14,963.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,500.00

Report Ref No. CC6/CTI20013217/Drs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1107U

INSPECTION








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1107U

RE-INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1107U

RE-INSPECTION









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R










LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

