

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 30-Nov-20

INSURANCE: Alfa China Taping


MODEL: HYUNDAI I40

VEHICLE NO.: SHA 1107 U

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR FENDER <i>Dent</i>	1	\$2,171.40	\$2,171.40	✓
REAR WINDSCREEN MOULDING <i>Nec</i>	1	\$51.80	\$51.80	✓
REAR DOOR (LH) <i>Dent</i>	1	\$2,201.10	\$2,201.10	✓
ROCKER PANEL OUTER GARNISH (LH) <i>scw</i>	1	\$732.80	\$732.80	X
BONNET <i>HW</i>	1	\$2,265.90	\$2,265.90	X
BONNET HINGE (LH/RH) <i>HW</i>	2	\$126.70	\$253.40	X
BONNET INSULATOR <i>HW</i>	1	\$202.50	\$202.50	X
BONNET INSULATOR CLIP 10 PCS <i>HW</i>	1	\$36.80	\$36.80	X
BONNET INSULATOR CLIPS <i>HW</i>	1	\$15.00	\$15.00	X
FRONT BUMPER COVER <i>st</i>	1	\$1,052.20	\$1,052.20	✓
FRONT BUMPER REINFORCEMENT <i>HW</i>	1	\$588.40	\$588.40	X
FRONT BUMPER BRACKET (LH/RH) <i>HW</i>	2	\$49.20	\$98.40	X
FRONT BUMPER RETAINER MOUNTING <i>HW</i>	1	\$76.20	\$76.20	X
HEADLAMP SUPPORT PANEL ASSY <i>2 HW</i>	1	\$907.40	\$907.40	X
HEADLAMP (LH) <i>cut (mostly broken)</i>	1	\$2,776.00	\$2,776.00	X
HEADLAMP SUPPORT TOP COVER <i>HW</i>	1	\$222.60	\$222.60	X
FRONT FENDER (LH) <i>Dent</i>	1	\$566.30	\$566.30	✓
FRONT FENDER APRON PANEL (LH) <i>2 HW</i>	1	\$637.00	\$637.00	X
FRONT FENDER SHIELD (LH) <i>2 SVL</i>	1	\$174.90	\$174.90	X
FRONT DOOR MIRROR SIDE GARNISH <i>HW</i>	1	\$225.00	\$225.00	X
FRONT DOOR MIRROR (LH) <i>broken</i>	1	\$670.00	\$670.00	✓
FRONT DOOR (LH) <i>Dent</i>	1	\$2,256.40	\$2,256.40	✓
FRONT DOOR HINGE UPPER (LH) <i>HW</i>	1	\$113.60	\$113.60	X
FRONT DOOR HINGE LOWER (LH) <i>HW</i>	1	\$125.70	\$125.70	X
FRONT WHEEL RIM (LH) <i>HW</i>	1	\$650.60	\$650.60	X
KNUCKLE ARM (LH) <i>2 distaste</i>	1	\$595.90	\$595.90	X
FRONT WHEEL BEARING HUB ASSY (LH) <i>2 Dent</i>	1	\$673.20	\$673.20	✓
FRONT SUSPENSION LOWER ARM (LH) <i>2 distaste</i>	1	\$1,104.00	\$1,104.00	✓
FRONT SHOCK ABSORBER ASSY (LH) <i>HW distaste</i>	1	\$684.40	\$684.40	✓
FRONT SHOCK ABSORBER MOUNTING (LH) <i>HW</i>	1	\$217.60	\$217.60	X
STG TIE ROD (LH) <i>HW</i>	1	\$186.40	\$186.40	X
STG TIE END (LH) <i>HW distaste</i>	1	\$125.20	\$125.20	X
STABILIZER BAR ASSY <i>HW</i>	1	\$463.70	\$463.70	X
STABILIZER BAR LINK (LH) <i>HW</i>	1	\$68.10	\$68.10	X
ABS SENSOR <i>HW</i>	1	\$217.90	\$217.90	X
FRONT DRIVE SHAFT (LH) <i>HW</i>	1	\$2,061.60	\$2,061.60	X
RACK & PINION ASSY <i>HW</i>	1	\$1,820.00	\$1,820.00	X
<b>SUB TOTAL</b>			<b>\$27,289.40</b>	
<b>LESS 20%</b>			<b>\$5,457.88</b>	
<b>DISCOUNTED TOTAL</b>			<b>\$21,831.52</b>	
REAR WINDSCREEN SEALANT <i>Nec</i>	SN 1	\$46.00	\$46.00	✓

Rear Door Comfortdelgro & Apps Sticker(LH) <i>hcc</i> SN	1	\$ 80.00	\$ 80.00	✓
FRONT DOOR COLOURED COMFORT LOGO <i>hcc</i> SN	1	\$75.00	\$75.00	✓
FRONT TYRE (LH) <i>hcc</i> SN	1	\$216.00	\$216.00	X
<b>SUB TOTAL</b>			<b>\$417.00</b>	
<b>Labour Charge</b>				
Panel Beating	1	\$1,600.00	\$1,600.00	900/-
Spray Painting Charge	1	\$1,400.00	\$1,400.00	900/-
Wiring Charge	1	\$160.00	\$160.00	30/-
Tuff Kote	1	\$180.00	\$180.00	40/-
Towing Charge	1	\$80.00	\$80.00	N/A
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$120.00	80/-
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	150/-
Re-set Frt ABS System	1	\$200.00	\$200.00	} 150/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	
<b>TOTAL LABOUR</b>			<b>\$4,970.00</b>	
<b>ESTIMATE TOTAL</b>			<b>\$ 27,218.52</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

02/12/2020 @ 1700hrs  
 Not Approved  
 L/Sure 7 days.  
  
 LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# BIFROST AUTO PTE LTD

## REPAIR SUPPLEMENTARY

DATE: 7-Dec-20

INSURANCE: China Tc-pny

MODEL: HYUNDAI I40

VEHICLE NO.: SHA 1107 U (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TYRE RIM (LH) <i>new</i>	1	\$650.60	\$650.60
REAR TYRE WHEEL CAP <i>new</i>	1	\$214.20	\$214.20
REAR WHEEL BEARING ING & HUB <i>Dist</i>	1	\$724.00	\$724.00
REAR TRAILING ARM (LH) <i>dist</i>	1	\$384.00	\$384.00
REAR ASSIST (LH) <i>dist</i>	1	\$219.40	\$219.40
REAR SHOCK ABSORBER (LH) <i>dist</i>	1	\$683.70	\$683.70
REAR UPPER ARM (LH) <i>dist</i>	1	\$335.75	\$335.75
REAR LOWER ARM (LH) <i>dist</i>	1	\$353.80	\$353.80
REAR KNUCKLE ARM (LH) <i>dist</i>	1	\$545.60	\$545.60
<b>SUB TOTAL</b>			<b>\$4,111.05</b>
<b>LESS 20%</b>			<b>\$822.21</b>
<b>DISCOUNTED TOTAL</b>			<b>\$3,288.84</b>

X  
X  
✓  
✓  
✓  
✓  
✓  
✓  
✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*[Signature]*  
Mya

2kk Auto

*[Signature]*