




Rear Door Comfortdelgro & Apps Sticker(LH) <i>hcc</i>	SN	1	\$ 80.00	\$ 80.00	✓
FRONT DOOR COLOURED COMFORT LOGO <i>hcc</i>	SN	1	\$75.00	\$75.00	✓
FRONT TYRE (LH) <i>hcc</i>	SN	1	\$216.00	\$216.00	X
<b>SUB TOTAL</b>					
				<b>\$417.00</b>	
<b>Labour Charge</b>					
Panel Beating					
Spray Painting Charge		1	\$1,600.00	\$1,600.00	900/-
Wiring Charge		1	\$1,400.00	\$1,400.00	900/-
Tuff Kote		1	\$160.00	\$160.00	30/-
Towing Charge		1	\$180.00	\$180.00	40/-
Remove/Refix Rear Windscreen Glass		1	\$80.00	\$80.00	NH
Transfer of Door Mechanism FRONT		1	\$120.00	\$120.00	80/-
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00	60/-
Four Wheel Alignment		1	\$80.00	\$80.00	60/-
Remove/Refix Undercarriage (Frt)		1	\$120.00	\$120.00	60/-
Re-set Frt ABS System		1	\$400.00	\$400.00	150/-
Diagnostic & Resetting To Erase Fault Code		1	\$200.00	\$200.00	150/-
			\$550.00	\$550.00	150/-
<b>TOTAL LABOUR</b>					
				<b>\$4,970.00</b>	
<b>ESTIMATE TOTAL</b>					
				<b>\$ 27,218.52</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

02/12/2020 @ 1700hrs  
 NA Antenna  
 L/Sum 9 days.  
 Mja  
 LKK Auto

12848.36  
 Supp. 2114.84  
 14963.20  
 L/S 11,500/-



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# BIFROST AUTO PTE LTD

## REPAIR SUPPLEMENTARY

DATE: 7-Dec-20

MODEL: HYUNDAI I40

INSURANCE: China Topway

VEHICLE NO.: SHA 1107 U (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TYRE RIM (LH) <i>new dist</i> 325-30	1	\$650.60	\$650.60
REAR TYRE WHEEL CAP <i>dist</i> 107-10	1	\$214.20	\$214.20
REAR WHEEL BEARING ING & HUB <i>dist</i> 362.00	1	\$724.00	\$724.00
REAR TRAILING ARM (LH) <i>dist</i> 192.00	1	\$384.00	\$384.00
REAR ASSIST (LH) <i>dist</i> 145.70	1	\$219.40	\$219.40
REAR SHOCK ABSORBER (LH) <i>dist</i> 276.30	1	\$683.70	\$683.70
REAR UPPER ARM (LH) <i>dist</i>	1	\$335.75	\$335.75
REAR LOWER ARM (LH) <i>dist</i>	1	\$353.80	\$353.80
REAR KNUCKLE ARM (LH) <i>dist</i>	1	\$545.60	\$545.60
<b>SUB TOTAL</b>			<b>\$4,111.05</b>
<b>LESS 20%</b>			<b>\$822.21</b>
<b>DISCOUNTED TOTAL</b>			<b>\$3,288.84</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*[Signature]*  
Ryan

2KK Auto

*[Signature]*

2643.55

202. 2114.84