



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 04/01/2021

User ID : CatherineLee

### Section A - Accident Details

Registration Number	SMB148T
Case Reference Number	BUS/11/20/1057
Registration Date	14/3/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Chng Kok Wah
Type of Accident	Side Swipe
Accident Date and Time	27/11/2020 3:38 PM
Accident Reported Date and Time	1/12/2020 2:39 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109026
Special Instruction to ARC, if any	SMB148T-RIGHT REAR PORTION Q3C (TP) INSURED WITH
Prepared Date and Time	1/12/2020 3:39 PM
Chassis Number	WEB62808323120703
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$795.00
Total Spray Cost	\$786.00	\$616.00
Total Spare Part Cost	\$4,591.69	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$6,437.69</b>	<b>\$1,411.00</b>
<b>Lump Sum Total</b>	<b>\$6,450.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	01/12/2020 3:57 PM	03/12/2020 4:12 PM
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/01/2021

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	\$795.00 ✓
<b>Total Labour</b>	<b>\$1,060.00</b>	<b>\$795.00</b>

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	\$616.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$786.00</b>	<b>\$616.00</b>

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009909	BODY RH		BUMPER:REAR,RH,FOR MB CITARO O530	1.00	\$837.84	100.00	\$0.00	Replace	Repair X R
6010012	VE	0005446911	LAMP, SIDE MARKER:FOR MB CITARO O530 BUS	0.00	\$94.50	0.00	\$0.00	Replace	Not Given X SVC
6010141	ENGINE	6287503206	FLAP,RADIATOR:FOR MB CITARO O530	1.00	\$5,445.00	100.00	\$0.00	Replace	Repair X R
<b>Total</b>					<b>\$6,377.34</b>		<b>\$0.00</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

p/p  
\$1,411  
3 days

795  
616  

---

1,411