

Authorized signatory and company stamp

CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240

ESTIMATE

Company Reg No. 200609327M GST Reg No. MR-8500111-X

	Invo	ice Name & Address				ame & Vehicle		
				Cust No/Name	FCV01884/MR	TAN TECK B	ENG	
Т	AN TECK BEI	NG		Reg No/Reg Date	SMS9250G	/ 20/03/20	20	
В	BLK 325 HOU	GANG AVE 7		Date In/Mileage	/	0		
#11-311				Chassis No	VF73AHNSRKJ674615			
S	SINGAPORE 5	30325		Engine No	10XVAY14322	40		
_	Dantast Na			Make/Model	CIT/GRAND C	4 SPACETOUR	ER 1.2 EU	RO 6.2
C	Contact No			Colour/Trim	MOE SOFT SA		6F TERPA	
Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
FCV01884	CRDVCH	28/11/2020/ 12:26		442 / CocoLu		15928		
		Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
E PNT88000					-			760.00
RENEW RE	EAR BUMPER							750.00
E PNT98000	AINT FOR RE	AR BUMPER						20.00
M SUNDRY	MINI FOR INE	.,,,,,						20.00
Sundry								
							ļ	
			Q.	יוויה	246			
			Si					
			St					
			St	ilma	ate			
			St					
			St					
			St					
			Sį					
			Si					
			St		ate			
			St					
			St					
			Sī					
			Sī					
			Sī					
			SI		ate			
			St					
			Si					
Confirm &	accepted by		St		Parts Labour			0 1,510

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or chaque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Specialist Job

Sundry/Others

Total (w/o GST)

Diagnostics Job

0.00

0.00

20.00

1,530.00