

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305436698

Date : 04/12/20

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive, Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No : SHA2554E

Date of Accident : 28-Nov-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: LONPAC --- GBF9237U
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$950.00
Final Lumpsum Repair cost \$950.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : NAZ

Date : 4/12/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LONPAC (45)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305436698
REGN NO : SHA2554E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 30.11.2020 12:40
ACCIDENT DATE : 28.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0595-G	REAR DOOR RH	1	2,201.10	20.00	1,760.88	X R
0002	28-01-9999-2023-A	REAR DOOR APPS STICKER RH	1	80.00		80.00	/ N E L
0003	04-01-0103-0658-G	REAR WHEEL CAP RH	1	217.20	20.00	173.76	/ C R K
						SUB-TOTAL : 2,014.64	

JOB NATURE

0000 20-05	Rear Door Adv.Sticker RH	100.00	/ NEL
0001 20-05	Rear Fender Adv.Sticker RH	100.00	/ NEL
0002 PB	PANEL BEATING-Rear Fender RH	600.00	280 280
0003 SP	SPRAYPAINT CHARGE	750.00	400
0004 20-00	TUFF COAT ON AFFECTED PARTS.	100.00	40
0005 L	TRANSFER OF DOOR	120.00	X NN
		SUB-TOTAL : 1,770.00	

LONPAC

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305436698
 REGN NO : SHA2554E
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 29.12.2016
 DATE/TIME IN : 30.11.2020 12:4
 ACCIDENT DATE : 28.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,784.64

Lmfs

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

NA2 CLK

2/12/2020 1630

LIS

2 DAYS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS AFTER 20% \$173.76

S/VERT \$280.00

LABOUR \$720.00

TOTAL \$1,173.76

LESS LIS 20% \$ 939.00

LIS TOTAL \$ 950.00 / 2 DAYS