

CHOO MOTOR SPRAY PAINTER

PAGE 1 OF 2

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Reg No: 22736900M

Estimate : 22116

Date : 01.12.2020

Vehicle Num : SLA 9800B

Make/Model : TOYOTA CAMRY

Chassis/Engine no :

Accident Date : 30.11.2020

Claim No : 1220-22116

Reference :

Policy No :

TP III
Jasper
MP20S3BK4107042653

Qty	Particular	Amount S\$
<u>List Item</u>		
1 pc	Rear boot <i>Distal</i>	\$ 1,012.30 ✓
1 pc	Rear boot lock <i>Distal</i>	\$ 892.20 381 ✓
1 pc	Rear boot centre emblem <i>ne</i>	\$ 77.40 ✓
1 pc	Rear boot emblem (camry) <i>ne</i>	\$ 58.50 ✓
1 pc	Rear boot emblem (2.0) <i>ne</i>	\$ 48.20 ✓
1 pc	Rear boot centre emblem <i>ne</i>	\$ 77.40 ✓
2 pc	Rear boot reflector lamp @ 399.40 <i>LH at, RH could</i>	\$ 798.80 660 ✓
1 pc	Rear boot rubber <i>at</i>	\$ 207.30 ✓
2 pc	Rear tail lamp @ 495.70 <i>LH at, RH smashed</i>	\$ 991.40 ✓
2 pc	Rear tail lamp lower bracket @ 25.20 <i>RH could</i>	\$ 50.40 25.20 ✓
1 pc	Rear end panel <i>Distal</i>	\$ 647.30 ✓
1 pc	Rear end panel top garnish <i>Distal</i>	\$ 421.30 383 ✓
2 pc	Rear fender @ 1230.20 <i>RH Braked</i>	\$ 2,460.40 1230.20 ✓
2 pc	Rear fender inner garnish @ 434.30 <i>RH Distal</i>	\$ 868.60 388 ✓
1 pc	Rear spare tyre panel <i>Reg</i>	\$ 1,023.60 ✓
1 pc	Rear spare tyre panel top cover board <i>tom</i>	\$ 244.80 ✓
1 pc	Rear bumper <i>Distal</i>	\$ 725.50 580 ✓
2 pc	Rear bumper side retainer @ 103.10 <i>RH Distal</i>	\$ 206.20 65 ✓
1 pc	Rear bumper towing cover <i>then</i>	\$ 26.50 ✓
1 pc	Rear bumper reinforment <i>But</i>	\$ 561.30 ✓ 392
2 pc	Rear bumper reflector @ 65.20 <i>RH could</i>	\$ 130.40 ✓ 65.20
1 pc	Rear exhaust silencer <i>Ne</i>	\$ 981.70 ✓
2 pc	Rear exhaust rubber @ 60.80 <i>ne</i>	\$ 121.60 ✓
1 pc	Rear exhaust chrome tail pipe <i>at</i>	\$ 98.70 ✓
List Item Total :		\$ 12,731.80
Discount 25 %		\$ 3,182.95
		\$ 9,548.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CHOO MOTOR SPRAY PAINTER

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Reg No: 22736900M

Estimate : 22116

Date : 01.12.2020

Vehicle Num : SLA 9800B

Make/Model : TOYOTA CAMRY

Chassis/Engine no :

Accident Date : 30.11.2020

Claim No : 1220-22116

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
12pc	Rear fender inner garnish clips @ 6.50 <i>mr</i>	\$ 78.00 30
3 pc	Rear end panel top garnish clips @ 6.50 <i>mr</i>	\$ 19.50 ✓
1 pc	Rear end panel sealant <i>mr</i>	\$ 80.00 60
1 pc	Rear glass sealant <i>mr</i>	\$ 100.00 60
1 set	Rear bumper reverse sensor <i>D-gd</i>	\$ 350.00 200
Special Nett Total :		\$ 627.50
<u>Labour Charge :</u>		
	To check wiring	\$ 180.00 30
	Tuff kote	\$ 150.00 100
	Remove and refix upholstery and roof lining	\$ 160.00 80
	Remove and replace exhaust pipe	\$ 160.00 +
	Remove and replace reverse sensor	\$ 160.00 50
	To remove and replace spare part and panel beating	\$ 1,500.00 1200
	To spray painting and etc	\$ 1,500.00 1100
Labour Charge Total :		\$ 3,810.00

E & O . E

Total Amount : \$ 13,986.35

CHOO MOTOR SPRAY PAINTER

Action L
L/S 01/12/20
09 Days
Total: 8654.17
L/S: 6SK