



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /WONG SOOK LENG Reg No/Reg Date SMC8687X / 26/07/201 Date In/Mileage 01/12/2020/ 0 Chassis No MMBSTA13AJH002253 Engine No 3A92UGY1382 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	01/12/2020/ 14:22	QUK	282 / Kevin Leong	60261			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								450 900.00
REPLACE FRT BUMPER, BODY KIT & AFFECTED AREA 450								
E PNT98000								350 700.00
PAINT WORK ON FRT BUMPER & BODY KIT 350								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								50.00
M SUNDRY								
TO SUPPLY FRT NUMBER PLATE WITH FRAME								20 50.00
M SUNDRY								
SUNDRIES								
M UNPAINTED BODYKITS X ? X NM					1.00	1643.00	20.00	1314.40
M HEADLAMP ASSY, LH					1.00	660.00	23.00	508.20
M FACE, FR BUMPER / BR					1.00	703.00	23.00	541.31
M COVER, HEADLAMP SUPT PANEL ? X NM					1.00	62.00	23.00	47.74
M GRILLE, FR UNDER / BR					1.00	165.00	23.00	127.05
M BRACKET, FR BUMPER, LH ? X NM					1.00	13.00	23.00	10.01
M AIR DAM, SIDE, FR LH ? X NM					1.00	18.00	23.00	13.86
M GRILLE, RADIATOR / BR					1.00	554.00	23.00	426.58
M MARK, THREE-DIA / nec					1.00	69.00	23.00	53.13
M REINFORCEMENT, FR BUMPER ? X NM					1.00	466.00	23.00	358.82

Estimate

Store (LKK)

00 - NM All

Excess - ?

6 days

2/12/20, 1.30pm

P/P

Estimate

stere (LKK) OD - N/A AL
 Excess - ?
 6 days
 2/12/20, 1.39pc
 P/P

Confirm & accepted by

M B L S L

7% GST on 5251.10
 Total Payable 5,618.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Authorized signatory and company stamp

Parts prices are subject to confirmation.
 Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 10% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.