LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jenny Lew Date: 24 Feb 2021

Preliminary Advice

Insured Vehicle No : SMN5436R

TP Vehicle No : SGF7231P Accident Date : 29/11/2020 Make : HONDA FIT Assignment Date : 02/12/2020

Date of Inspection : 02/12/2020 Est. Duration of Repair : 4

Inspection At : J-MART MOTOR PTE LTD (HQ)

BLK 5 DEFU LANE 10, #01-578

SINGAPORE 539186

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,733.76
Revised Amount	:S\$	2,452.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,452.56
Lump Sum Repair	:S\$	1,950.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: SURVEY ON WP