



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV12530/Mr Pang Chuan Hung (Fang Zhuang)
	Reg No/Reg Date	SMQ8861K / 09/12/201
	Date In/Mileage	/ 0
	Chassis No	MMB5TA13AKH003362
	Engine No	3A92UJB1635
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	01/12/2020/ 16:31	QUK	282 / Kevin Leong	60266		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BODYKIT & AFFECTED AREA REPAIR ON REAR LH FENDER - R				450			1800.00
E PNT98000 PAINT WORK ON REAR BUMPER, BODY KIT & REAR LH FENDER				350			1050.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST							120.00
M SUNDRY PERFORM RUST PREVENTION							80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUNDRIES							50.00
M LAMP ASSY, COMB, RR LH				1.00	335.00	23.00	257.95
M BRACKET, RR BUMPER, LH				1.00	28.00	23.00	21.56
M FACE, RR BUMPER				1.00	748.00	23.00	575.96
M UNPAINTED BODYKITS				1.00	1643.00	20.00	1314.40

Estimate

Steve (LKK) OD - Ab1 Authn
Excess - ?
3/12/20, 1.30pm
3 Lys
P/P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	5,419.87
7% GST on	5419.87	379.39
Total Payable		5,799.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.