

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV12530/Mr Pang Chuan Hung (Fang Zhuang
	Reg No/Reg Date	SMQ8861K / 09/12/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AKH003362
	Engine No	3A92UJB1635
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	01/12/2020/ 16:31	QUK	282 / Kevin Leong	60266

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BODYKIT & AFFECTED AREA REPAIR ON REAR LH FENDER				1800.00
E PNT98000 PAINT WORK ON REAR BUMPER, BODY KIT & REAR LH FENDER				1050.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				120.00
M SUNDRY PERFORM RUST PREVENTION				80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				50.00
M LAMP ASSY,COMB,RR LH	1.00	335.00	23.00	257.95
M BRACKET,RR BUMPER,LH	1.00	28.00	23.00	21.56
M FACE,RR BUMPER	1.00	748.00	23.00	575.96
M UNPAINTED BODYKITS	1.00	1643.00	20.00	1314.40

Confirm & accepted by

7% GST on	Nett 5419.87	5,419.87
		379.39
Total Payable		5,799.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.