

Lee / W Admin

K. ki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 88189365

TP chinu.
Xiao Chem

ESTIMATE

Repair Code : CLM16568
 Date in : 20/11/2020
 Vehicle Num. : SLT2676P
 Model : HONDA VEZEL 1.5X HYBRID A
 Chassis/Eng# : RU31251702/LEB5951719

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>deformed.</i>	1	801.70	✓ 801.70
FRONT BUMPER LOWER LID GARNISH <i>torn</i>	1	381.00	✓ 381.00
FRONT BUMPER RH FOGLAMP COVER <i>dehd</i>	1	45.00	✓ 45.00
FRONT BUMPER SIDE RETAINER L/R <i>RH dm d</i>	2	20.60	20.60 41.20
FRONT RH FENDER <i>dentec</i>	1	580.00	✓ 580.00
FRONT RH FENDER 'HYBRID' EMBLEM <i>nu</i>	1	58.00	✓ 58.00
FRONT RH FENDER ARCH GARNISH <i>ut</i>	1	220.00	✓ 220.00
FRONT RH FENDER BRACKET <i>no nec</i>	1	42.00	x 42.00
FRONT RH FENDER INNER SHIELD <i>392580</i>	1	130.00	x 130.00
FRONT RH HEADLAMP <i>crashed</i>	1	1784.50	✓ 1,784.50
FRONT RH HEADLAMP LOWER BRACKET <i>crashed</i>	1	35.00	✓ 35.00
WASHER TANK <i>no nec</i>	1	75.00	x 75.00
Subtotal before discount			4,193.40
Percentage discount 20%			838.68
Sub-total 1			3,354.72
FRONT BUMPER CLIPS - SET <i>nu</i>	1	50.00	50 50.00
FRONT RH FENDER ARCH GARNISH CLIPS - SET <i>nu</i>	1	30.00	✓ 30.00
FRONT RH FENDER INNER SHEILD CLIPS - SET <i>no nec</i>	1	50.00	x 50.00

60

*** This is a computer-generated document which requires no signature.***

N51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 88189365

ESTIMATE

Repair Code : CLM16568
 Date in : 20/11/2020
 Vehicle Num. : SLT2676P
 Model : HONDA VEZEL 1.5X HYBRID A
 Chassis/Eng# : RU31251702/LEB5951719

	Subtotal before discount	130.00
Percentage discount	0%	0.00
	Sub-total 2	130.00
	Parts-total	3,484.72

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

	Labour Total	1,300.00
	Parts & Labour Total	4,784.72

830
 30 50.00
 400 700.00
 400 500.00
 X. 50.00

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____

total: 4030.64
 h/s: 3.2k ✓
 04 Days.