

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0936/2020/NS
DATE	:	1-Dec-20
WIP	:	60659

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR LEE TECK WAI(LI DEWEI)
ADDRESS	:	23 GHIM MOH LINK #02-222 SINGAPORE 271023
TELEPHONE	:	HP +65 82223814
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070128239
VEHICLE NO	:	SMV 2946 M
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR	:	24/9/2020
ENGINE NO	:	CVK 086198
CHASSIS NO	:	WAUZZZF46KA104403
MILEAGE	:	1-Dec-20
DATE IN	:	2690KM
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	30-Nov-20
PLACE OF ACCIDENT	:	CTE BEFORE 7C/7D EXIT AREA

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2946 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULE. <i>250 x 2</i>	S/N \$ 700.00	<i>500</i>
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00 /	
4	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00 X	
SUB TOTAL LABOUR CHARGES		: <u>\$ 2,660.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 2946 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	✓ TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO DISMANTLE AND REINSTALL RHS WING MIRROR ASSY. * LH door add labour (Spp) (photo)	S/N \$ 350.00	280
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT DOOR AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. 500 x 5	\$ 5,600.00	2500
7	1- RH only TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS. 12 550 x 5	\$ 6,900.00	2750
8	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		: \$ 15,894.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER / <i>DR</i>	\$	2,171.00 /	1736.80
2 FRONT BUMPER FIXING PARTS ? <i>X NM</i>	\$	580.00	
3 FRONT BUMPER SECURING STRIP ? <i>X NM</i> 2	\$	70.00	
4 FRONT BUMPER GRILLE - CENTRE ? <i>X NM</i>	\$	194.00	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X NM</i>	\$	208.00	
6 RADIATOR GRILLE / <i>DR</i>	\$	1,317.00 /	1053.60
7 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>(RH)</i> / <i>DR</i> 2, 1	\$	268.00	106.80 /
8 FRONT PARKING AID SENSOR - INNER/OUTER 2	\$	484.00	<i>? X NM</i>
9 FRONT PARKING AID SEAL RING <i>X NM</i> 4	\$	14.00	
10 FRONT BUMPER WIRING SET ? <i>X NM</i>	\$	505.00	
11 FRONT BUMPER CARRIER / <i>DO</i>	\$	795.00 /	635.60
12 FRONT BUMPER FOAM FILLER PIECE / <i>DR</i>	\$	123.00 /	98.40
13 FRONT BUMPER COVER <i>(Top (LH) - (RH))</i> / <i>CR4</i>	\$	126.00 /	100.40
14 FRONT BUMPER BRACKET - LH/RH ? <i>X NM</i> 2	\$	450.00	
15 FRONT BUMPER GUIDE SECTION - LH/RH ? 2	\$	72.00	<i>X NM</i>
16 CAUTION SIGN STICKER / <i>NR</i> NEC	\$	14.00 /	10.80
17 AIRCON STICKER / <i>MC</i> NEC	\$	8.00 /	5.68
18 LOCK CARRIER BRACKET - LH/RH	\$	136.00 /	108.40
19 LOCK CARRIER BRACKET SUPPORT - <i>(LH/RH)</i> / <i>CR4</i> 2	\$	56.00 /	44.48
20 HORN - LH HIGH TONE <i>X NM</i>	\$	124.00	
SUB TOTAL SPARE PARTS :		\$ 7,715.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 HORN - RH LOW TONE X NAI		\$ 124.00	
22 SPRING SHACKLE - LH/RH ? X NAI	2	\$ 58.00	
23 BONNET / DD		\$ 2,763.00 /	2210.40
24 BONNET ATTACHMENT PARTS X NM		\$ 408.00	
25 BONNET LID HINGE - LH/RH ? X NAI	2	\$ 602.00	
26 BONNET IMPACT PROTECTION - CENTRE / CRU		\$ 27.00 /	21.52
27 BONNET IMPACT PROTECTION - LH / NK		\$ 28.00 /	21.84
28 BONNET IMPACT PROTECTION - RH / NK		\$ 27.00 /	21.52
29 BONNET STRIKER - LH/RH X NM	2	\$ 100.00	
30 BONNET LID LOCK X NM	2	\$ 424.00	
31 BONNET BOWDEN CABLE - CENTRE ? X NAI		\$ 57.00	
32 BONNET BOWDEN CABLE ? / BT		\$ 57.00 /	45.52
33 BONNET RELEASE LEVER X NM		\$ 13.00	
34 BONNET LID LOCK CABLE X NAI		\$ 73.00	
35 PLNEUM CHAMBER COVER X NAI		\$ 96.00	
36 BONNET SOUND ABSORBER X NAI		\$ 339.00	
37 LED HEADLIGHT - LH/RH / BR	2	\$ 15,386.00 /	12308.80
38 LIFT CYLINDER - LH/RH ? X NM	2	\$ 416.00	
39 LIFT CYLINDER CORRUGATED PIPE ? X NAI		\$ 92.00	
40 LOCK CARRIER ? / CRA		\$ 1,004.00 /	803.20
SUB TOTAL SPARE PARTS	:	\$ 22,094.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 COOLANT REGULATOR SUPPORT ? X NM 2	\$	75.00	
42 AIRCON CONDENSER — PD	\$	615.00 /	492
43 REFRIGERANT LINE PRESSURE SENDER ? X NM	\$	181.00	
44 HIGH PRESSURE SWITCH VALVE ? X NM	\$	49.00	
45 REFRIGERANT LINE ? X NM	\$	245.00	
46 TEMPERATURE SENSOR BRACKET ? / MIS	\$	18.00 /	14.40
47 EXTERNAL TEMPERATURE SENSOR ? X NM	\$	56.00	
48 CHARGE AIR COOLER ? X NM	\$	580.00	
49 RADIATOR ? — BT	\$	837.00 /	669.20
50 READY MIX COOLANT ? — MC	\$	177.00 /	72.32
51 RADIATOR FAN RING ? X NM	\$	242.00	
52 RADIATOR FAN ? — SCR	\$	1,896.00 /	1516.80
53 RADIATOR AIR GUIDE - (LH) (RH) OUTER ? — CRA 2	\$	56.00 /	44.16
54 RADIATOR AIR GUIDE - (LH) (RH) INNER ? — CRA 2	\$	24.00 /	18.72
55 RADIATOR AIR GUIDE - UPPER ? X NM	\$	16.00	
56 RADIATOR AIR GUIDE - LOWER ? X NM	\$	22.00	
57 AIR INTAKE AIR DUCT - RH ? X NM	\$	22.00	
58 AIR INTAKE AIR GUIDE ? — BR	\$	53.00 /	41.92
59 AIR INTAKE HOSE ? X NM	\$	94.00	
60 AIR MASS METER ? X NM	\$	551.00	
SUB TOTAL SPARE PARTS :		\$ 5,809.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 2946 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
61 FRONT DOOR - LH X R		\$	2,354.00	
62 FRONT DOOR OUTER SEAL - LH X NM	NEC	\$	203.00	
63 BONDING AGENT X NM	NEC	\$	47.00	
64 CLEANING SOLUTION X NM	NEC	\$	65.00	
65 FRONT DOOR ATTACHMENT PARTS X NM		\$	870.00	
66 FRONT DOOR CATCH X NM		\$	104.00	
67 WINDOW SLOT SEAL - (LH/RH) - CUT 2 1/2		\$	606.00	✓ 484.80
68 WINDOW GUIDE TRIM STRIP - LH/RH X NM 2		\$	508.00	
69 FRONT NO PLATE ✓ BT	S/N	\$	60.00	✓
70 SUNDRIES ? NRC		\$	400.00	✓ 2.24
TOTAL SPARE PARTS	:	\$	40,835.00	
TOTAL LABOUR CHARGES	:	\$	15,894.00	
GRAND TOTAL	:	\$	56,729.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve CLKK)
: 00 - NH AL
: Excess - ?
: 2/12/20, 12th days
: P/P, My PC SH

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT