

Not Authored
\$ 1772.70

ROEL

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD899H - CHINA

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD899H - ROEL

WDD2120012B224285

MERCEDES BENZ

E220 CDI

29.03.2017

CHINA

PART			LIST	
1	1	Front Bumper	\$	Dis 1,265.00 ✓
2	1	Front Bumper Reinforcement	\$	R 656.00 X
3	1	Front Bumper Shock Absorber	\$	Sn 248.00 X
4	1	Front Bumper Fog Lamp LH	\$	Sn 272.00 ✓
5	1	Front Bumper Fog Lamp Garnish LH	\$	Sn 68.00 X
6	1	Front Bumper Side Retainer LH	\$	R 88.00 ✓
7	1	Front Bumper Side Bracket LH	\$	R 40.00
8	1	Front Bumper Side Inner Frame LH	\$	Sn 46.00
9	1	Radiator Grille	\$	Sn 632.00
10	1	Bonnet	\$	R 2,912.00
11	1	Bonnet Hinge LH	\$	R 101.00
12	1	Bonnet Hinge RH	\$	R 101.00
13	1	Front Headlamp LH	\$	Sn 944.00
14	1	Front Headlamp Panel LH	\$	R 120.00
15	1	Front Headlamp Brace LH	\$	R 96.40
16	1	Front Fender LH	\$	R 865.31
17	1	Front Fender Inner Cowling LH	\$	Sn 76.00
18	1	Front Shock Absorber LH	\$	Sn 692.00
19	1	Front Upper Arm LH	\$	Sn 544.00
20	1	Front Lower Arm LH	\$	Sn 748.00
21	1	Front Knuckle Arm LH	\$	Sn 1,152.00
22	1	Rocket Panel	\$	Sn 935.00
23	1	Front Door LH	\$	R 1,840.00 ✓

TOTAL	\$	14,441.71
10%	\$	1,444.17
	\$	12,997.54

Specical Nett

1	1 Set	Front Fender Inner Cowling Insert Clip	\$	R 40.00 X
2	1 Set	Front Bumper Clip	\$	R 40.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD899H - CHINA

3	1SET	Rocker panel Fastener Clip	\$	<i>nn</i>	40.00	} X
4	1	Door corporate sticker	\$	<i>nn</i>	80.00	
5	1SET	Door LEDGE Clip FTR LH	\$	<i>nn</i>	60.00	
6	1SET	Door LEDGE Clip RR LH	\$	<i>nn</i>	60.00	
7	2	Rear Windscreen selant	\$	<i>nn</i>	80.00	
8	1	Windscreen Moulding	\$	<i>nn</i>	120.00	
9	1	Front Tyre LH	\$	<i>Sh</i>	350.00	}
10	1	Front Alloy Rim LH	\$	<i>Sh</i>	850.00	

TOTAL	\$	1,720.00
TOTAL PARTS	\$	14,717.54

Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And
Renewal Of Parts, Adjust And Realign The

\$ 2,800.00 *2501*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *151*

To Remove And Refit Interior Fittings,
Trimings, Garnish, Fittings And Other, to

\$ *nn* 380.00 X

To Transfer Of Fender Fittings, Attachment
And Perform Water Seepage Test.

\$ *nn* 170.00 X

To Check Steering Geometry And Computer
Wheel Alignment.

\$ *nn* 220.00 X

Putty And Spray Painting Of The Affected
Portion.

\$ 3,000.00 *2501*

To Transfer Of Door Fittings, Attachment
And Perform Water Seepage Test.

\$ *nn* 170.00 X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is all
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

REPAIR DAYS

Acknowledged by Repairer

Signature:

Date:

TOTAL	\$	7,080.00
Over All Total	\$	21,797.54

10 DAYS*2 days*