



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15177/NUNNA SIVAJI RAO Reg No/Reg Date SMR4534B / 07/01/202 Date In/Mileage / 0 Chassis No GF7W0600952 Engine No 4J11AG9646 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/12/2020/ 11:35	QUE	261 / Edwin Caina	60285			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 / RENEW FRT BUMPER REPAIR LHF FENDER								450 1350.00
E PNT98000 / RESPRAY FRT BUMPER & LHF FENDER								350 700.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING								50.00
M SUNDRY Sundries								20.00
M FACE,FR BUMPER / BR					1.00	859.00	23.00	661.43
M BRACKET,FR BUMPER SIDE,LH / BR					1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,RH / BR					1.00	18.00	23.00	13.86
M EXTENSION,FR BUMPER (1mm) / CUT					1.00	509.00	23.00	391.93
M GARNISH,FR BUMPER,LH X NN					1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE X NN					1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE / CRA					1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE X NN					1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE X NN					1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE X NN					1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE X NN					1.00	112.00	23.00	86.24
M COVER,FR BUMPER / BR (Black)					1.00	359.00	23.00	276.43
M REINFORCEMENT,FR BUMPER					1.00	490.00	23.00	377.30
M BAR,FR BUMPER GUARD					1.00	130.00	23.00	100.10
M REINF,FR BUMPER SIDE,LH					1.00	60.00	23.00	46.20
M REINF,FR BUMPER SIDE,RH					1.00	69.00	23.00	53.13
M REINFORCEMENT,FR BUMPER					1.00	134.00	23.00	103.18
M GRILLE ASSY,RADIATOR / BR					1.00	548.00	23.00	421.96
M MOULDING,FR BUMPER,LH X NN					1.00	116.00	23.00	89.32

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15177/NUNNA SIVAJI RAO Reg No/Reg Date SMR45348 / 07/01/202 Date In/Mileage / 0 Chassis No GF7W0600952 Engine No 4J11AG9646 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/12/2020/ 11:35	QUE	261 / Edwin Caina	60285			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M MOULDING,FR WHEEL ARCH,LH X NN					1.00	160.00	23.00	123.20

Estimate

7/12/20, 12:00p

Steve CLKK

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	5,564.06
7% GST on	5564.06	389.48
Total Payable		5,953.54

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.