

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.12.2020

Time: 14:51:23

Page: 1

NTUC - 45
LKK

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305436693
 REGN NO : SHD3008T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 09.06.2016
 DATE/TIME IN : 30.11.2020 03:10
 ACCIDENT DATE : 30.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	de-
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	de-
0003 04-01-0103-0576-G	REAR FENDER LH	1	2,171.40	20.00	1,737.12	bue-
0004 04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	35.60	20.00	28.48	one-
0005 04-01-0103-0710-G	TAILLAMP PANEL LH	1	453.00	20.00	362.40	bt-
0006 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	one-
0007 03-01-0103-0121-G	REAR FENDER SHIELD LH	1	169.30	20.00	135.44	R un
0008 04-01-0103-0581-A	TAILLAMP LH	1	697.80	20.00	558.24	one-
0009 04-01-0103-0584-G	BOOTLID LAMP LH	1	1,131.20	20.00	904.96	R un
0010 02-01-0103-0053-G	EXHAUST MUFFLER LH	1	1,935.40	20.00	1,548.32	R un-
0011 05-01-0199-0032-A	WINDSCREEN AHESIVE-310MLC	2	92.00	10.00	82.80	one-
0012 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	10.00	122.13	R un.

SUB-TOTAL : 6,564.69

JOB NATURE

4713.80
 3771.04
 82.80.

NTUC - 45
LKK

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305436693
 REGN NO : SHD3008T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 09.06.2016
 DATE/TIME IN : 30.11.2020 0:
 ACCIDENT DATE : 30.11.2020

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT	
0000 20-05	Rear Fender Adv.Sticker LH/RH	200.00	250.
0001 20-05	Rear Bumper Adv.Sticker	50.00	
0002 PB	PANEL BEATING	900.00	840.
0003 SP	SPRAYPAINT CHARGE	1000.00	800.
0004 17-01	CHECK ALL LIGHTING	40.00	30
0005 20-00	TUFF COAT ON AFFECTED PARTS.	100.00	30.
0006 L	R/I UPHOLSTERY ETC	120.00	60.
0007 L	R/I REAR WINDSCREEN	150.00	120.
0008 L	R/I REVERSE SENSOR	120.00	30 - 1910
0009 23-01	TOWING FEE	0.00	

SUB-TOTAL : 2,680.00

3771.04
 82.80
 250
 1910
 6013.84
 4184800
 # 15 days