

VEHICLE NO SHB4732P

MAKE :

MODEL HYU- I40

CHIANG/ *ATMC*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		<i>de</i>	\$1,052.20
2	FRONT BUMPER BRACKET SIDE LH/RH		<i>RH de</i> \$44.80 <i>LH X</i>	\$71.20
10	FRONT BUMPER CLIPS		\$2.20 <i>rec</i>	\$22.00
1	FRONT BUMPER BRACKET LH/RH		\$49.20 <i>X</i>	\$98.40
1	FRT RH FENDER		<i>ht</i>	\$663.00
1	FRT RH HEAD LAMP ASSY		<i>aw</i>	\$1,388.00
1	HEAD LAMP SUPPORT PANEL		<i>ny</i> <i>X</i>	\$907.40
1	WASHER TANK ASSY		<i>ny</i> <i>X</i>	\$61.90
			<i>3170</i>	\$4,264.10
	20.00% DISCOUNTED TOTAL		<i>2536</i>	\$852.82
				\$3,411.28
	<b>Labour Charge</b>			
	Panel Beating		<i>420</i>	\$500.00
	Spray Painting Charge		<i>400</i>	\$500.00
	Check lighting		<i>30</i>	\$50.00
	Remove/refix condenser & charge gas		<i>ny X</i>	\$90.00
	Tuff Kote		<i>880</i> <i>30</i>	\$90.00
	<b>TOTAL LABOUR</b>			\$1,230.00
	<b>ESTIMATE TOTAL</b>		<i>3416</i> <i>1/5/2400</i> <i>3 days</i>	\$4,641.28
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Tanphi 97475748*  
*ur' 01/12/2024*  
*lumpsum 2-3 days*  
*Resurvey after repair*  
*tanphi@lkkauto.com*