

趙 源 摩 哆

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: Third Party

Date: 01.02.2020

Accident Date : 28.11.2020

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair "Honda Vezel" Reg. No. SKW913P Claiming Against Your Insured Veh. No. GBC4245U		
1pc	Bonnet		1,089.00 ✓
2pcs	Bonnet Side Stoppers		26.00 ✓
2pcs	Bonnet Rubber Seal	13.00	26.00 ✓
8pcs	Bonnet Insulator Clips	39.00	312.00 ✓
1pc	Headlamp LH	3.80	3.80 ✓
1pc	Grille Top Garnish		1,970.00 ✓
1pc	Grille Top Garnish Emblem		195.00 ✓
1pc	Grille Top Garnish Moulding LH		32.00 ✓
1pc	Front Bumper		150.00 ✓
14pcs	Front Bumper Clips		963.00 ✓
1pc	Front Bumper Reinforcement	3.80	3.80 ✓
	Less 20%		4,926.60
			985.32
			3,941.28
	Front Number Plate		45.00 SN ✓
	Labour Charge - Panel Beating, Repairing Of Bonnet Hinge, Brace Panel and Parts Replacement		300.00 200 ✓
	To Respray Affected Areas		480.00 400 ✓
		Total :	4,766.28

LKK Auto Consultants believe notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8 1869.76

Not Authorized
 Primary Repairer
 3 days

趙 源 摩 哆
Chew Goon Motor

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)

Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint

Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀ 修理各种汽车敲焊打吗咭喷漆等 ▶

MSIG Insurance (S) Pte Ltd

Accident Date : 28.11.2020

04.12.2020

Estimate Cost of Repair to "Honda Vezel" Reg. No. SKW913P
Claiming Against Your Insured Veh. No. GBC4245U

Supplementary

pc Headlamp Lower Bracket LH

Less 20%

sn
37.00 X
37.00
7.40

Grand Total :

29.60