

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SO LAN @FOO SO LAN
BLK 131A CANBERRA CRESCENT #02-536
SINGAPORE 751131

Contact : 98226284, 81884839

TP China
Veron.

ESTIMATE

Repair Code : CLM15109

Date in : 01/12/2020

Vehicle Num. : CB9928T

Model : TOYOTA HIACE 2.5 M

Chassis/Eng# : KDH2000030025/2KD1366321

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	706.00	✓ 706.00
REAR BUMPER LOWER BRACKET <i>Best</i>	4	48.00	72 192.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	47.00	✓ 94.00
REAR BUMPER STEP PANEL <i>Best</i>	1	381.90	✓ 381.90
REAR END PANEL (INNER) <i>Repair</i>	1	820.70	+ 820.70
REAR END PANEL (OUTER) <i>Dented</i>	1	743.00	✓ 743.00
REAR TAILGATE <i>Dented</i>	1	1950.00	✓ 1,950.00
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	63.00	✓ 63.00
REAR TAILGATE DAMPER L/R <i>new</i>	2	214.00	+ 428.00
REAR TAILGATE HINGES L/R <i>new</i>	2	67.00	+ 134.00
REAR TAILGATE INNER AUTO LOCK CONTROL <i>Reqd</i>	1	405.00	289 405.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	17.00	+ 34.00
REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	469.00	+ 469.00
REAR TAILGATE LOCK STRIKER <i>new</i>	1	53.00	+ 53.00
REAR TAILGATE MECHANISM LOCK <i>Reqd</i>	1	264.00	✓ 264.00
REAR TAILGATE MECHANISM LOCK COVER <i>ut</i>	1	98.90	✓ 98.90
REAR TAILGATE NUMBER PLATE LAMP L/R <i>new</i>	2	112.10	+ 224.20
REAR TAILGATE OUTER HANDLE <i>cracked</i>	1	93.00	✓ 93.00

*** This is a computer-generated document which requires no signature.***

page 1

Rear tailgate window
shutters

980.00 ✓

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SO LAN @FOO SO LAN

BLK 131A CANBERRA CRESCENT #02-536

SINGAPORE 751131

ESTIMATE

Repair Code : CLM15109

Date in : 01/12/2020

Vehicle Num. : CB9928T

Model : TOYOTA HIACE 2.5 M

Chassis/Eng# : KDH2000030025/2KD1366321

Contact : 98226284, 81884839

REAR TAILGATE WEATHER STRIP <i>lt</i>	1	391.00	✓	391.00
REAR TAILGATE WINDSCREEN SEAL <i>Nr</i>	1	80.00	✓	80.00
REAR TAILLAMP L/R <i>RH cml d</i>	2	265.00	265	530.00
REAR TAILLAMP LOWER GARNISH <i>Del d</i>	2	157.00	✓	314.00
REAR TAILLAMP LOWER GARNISH SIDE RETAINER <i>Nr m</i>	2	53.00	+	106.00
Subtotal before discount				8,574.70
Percentage discount 25%				2,143.68
Sub-total 1				6,431.03
REAR BUMPER CLIPS - SET <i>Nr</i>	1	50.00	30	50.00
REAR TAILGATE '70KM' STICKER <i>Nr</i>	1	25.00	15	25.00
REAR TAILGATE AWC STICKER <i>Nr</i>	1	35.00	25	35.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Nr m</i>	1	50.00	+	50.00
REAR TAILGATE NUMBER PLATE <i>Nr m</i>	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>Nr m</i>	1	50.00	+	50.00
REAR TAILGATE OUTER HANDLE CLIPS - SET <i>Nr</i>	1	50.00	10	50.00
REAR TAILGATE OUTER HANDLE STICKER - SET <i>Nr</i>	1	100.00	50	100.00
REAR TAILGATE WINDSCREEN SEALANT <i>Nr</i>	1	80.00	60	80.00
REAR TAILGATE WINDSCREEN SOLAR FILM <i>Nr</i>	1	200.00	✓	200.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SO LAN @FOO SO LAN
BLK 131A CANBERRA CRESCENT #02-536
SINGAPORE 751131

Contact : 98226284, 81884839

ESTIMATE

Repair Code : CLM15109

Date in : 01/12/2020

Vehicle Num. : CB9928T

Model : TOYOTA HIACE 2.5 M

Chassis/Eng# : KDH2000030025/2KD1366321

REAR TAILLAMP CLIPS L/R - SET	<i>m</i>	2	25.00	<i>10</i> 50.00
REAR TAILLAMP LOWER GARNISH CLIPS - SET	<i>m</i>	1	20.00	<i>10</i> 20.00
Subtotal before discount				735.00
Percentage discount 0%				0.00
Sub-total 2				735.00
Parts-total				7,166.03

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove/replace RH hydraulic cylinder jack (inner/outer) dust covers and etc.

Labour Total

2,410.00

Parts & Labour Total

10,311.03

9,576.03

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin
4/s 03/12/20
06 Days
total: 7298.60
4/s: 5.8K ✓