

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 08.12.20

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKR2850A**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 28.11.20
TIME OF ACCIDENT : 15:10HRS

Veron.
M2053REH104525860

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 495.00	\$ 495.00
2	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 147.00	\$ 147.00
3	FRONT BUMPER FOG LAMP RH <i>cancel</i>	1	\$ 320.00	\$ 320.00
4	FRONT BUMPER FOG LAMP GARNISH RH <i>cancel</i>	1	\$ 75.00	\$ 75.00
5	FRONT BUMPER SIDE RETAINER <i>new RH</i>	2	\$ 60.00	\$ 120.00
6	FRONT BUMPER REINFORCEMENT SPONGE <i>new</i>	1	\$ 123.00	\$ 123.00
7	FRONT CENTER GRILLE <i>3 new</i>	1	\$ 349.00	\$ 349.00
8	FRONT CENTER GRILLE LOGO <i>3 new</i>	1	\$ 85.00	\$ 85.00
9	HEADLAMP (LED) RH <i>lit.</i>	1	\$ 2,849.00	\$ 2,849.00
10	HEADLAMP LOWER BRACKET RH <i>not new</i>	1	\$ 95.00	\$ 95.00
11	FRONT FENDER RH <i>new</i>	1	\$ 782.00	\$ 782.00
12	FRONT FENDER EMBLEM (VVTI) RH <i>new</i>	1	\$ 55.00	\$ 55.00
13	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 210.00	\$ 210.00
14	FRONT FENDER UPPER CORNER GARNISH RH <i>new</i>	1	\$ 85.00	\$ 85.00
15	FRONT FENDER SUPPORT BRACKET <i>new</i>	1	\$ 90.00	\$ 90.00
16	FRONT KNUCKLE ARM RH <i>3 new</i>	1	\$ 585.00	\$ 585.00
17	FRONT LOWER ARM RH <i>3 new</i>	1	\$ 640.00	\$ 640.00
18	FRONT KNUCKLE ARM BEARING RH <i>3 new</i>	1	\$ 280.00	\$ 280.00
19	FRONT STABILIZER BAR LINKAGE RH <i>3 new</i>	1	\$ 195.00	\$ 195.00
20	FRONT SHOCK ABSORBER RH <i>3 new</i>	1	\$ 405.00	\$ 405.00
21	FRONT ABS SENSOR RH <i>3 new</i>	1	\$ 460.00	\$ 460.00
22	FRONT WHEEL RIM RH <i>new</i>	1	\$ 1,655.00	\$ 1,655.00

TOTAL PRICE \$ 10,100.00
LESS 25% \$ 2,525.00
SUB TOTAL PRICE \$ 7,575.00

3383

2537.25

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKR2850A**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 28.11.20
 TIME OF ACCIDENT : 15:10HRS

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
3	FRONT BUMPER FOG LAMP GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
4	FRONT CENTER GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
5	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
6	FRONT FENDER UPPER CORNER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
7	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
8	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 580.00	\$ 580.00 <i>+</i>

60

TOTAL \$ 950.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 600.00	<i>300</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 600.00	<i>250</i>
3	TUFF COAT	\$ 150.00	<i>x</i>
4	WIRING CHECK	\$ 80.00	<i>30</i>
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	<i>x</i>
6	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>x</i>
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

580

TOTAL \$ 2,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,525.00
 TOTAL LABOUR COST : \$ 2,080.00
 TOTAL REPAIR COST : \$ 10,605.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

Acknowledged by Repairer
 Signature:
 Date:

Admin
4/s 10/12/20
03 Days
total: 3177.25
4/s: 2.5K