

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ng Kwai Kay Francis

Date: 03 Dec 2020

Preliminary Advice

Vehicle No	: GBD7579G	Accident Date	: 08/08/2020
Make	: TOYOTA DYNA 1.5T	Policy No.	: MR003469
Assignment Date	: 02/12/2020	Excess	: S\$3,750.00
Date of Inspection	: 2/12/20	Est. Duration of Repair	:
Inspection At	: BH AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle caught fire. The caused of fire probably due to short-circuit at the wire harness.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	6,572.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,428.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :