



Your Ref : M2003858

Date: 04th December 2020

Our Ref : CS/TMI20013274/KDvd3e2

M/s Tokio Marine Insurance Singapore Ltd

20 Mccallum Street #09-01

Tokio Marine Centre

Singapore 069046

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBD 7579G
ACCIDENT ON 08/08/2020**

Instruction was received to inspect the vehicle Reg. No. GBD 7579G. The inspection was conducted on 02/12/2020 at the premises of M/s BH Auto Services Pte Ltd (Sin Ming), Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, Singapore 575636.

The following vehicle information was recorded:

Registration Number	: GBD 7579G
Make/Model	: Toyota Dyna 3.0 Diesel Turbo M/T 2WD Lorry
Year of Registration	: 2015
Body Colour	: Blue
Chassis Number	: KDY2318017429
Engine Capacity	: 2982 cc

The lorry caught fire. The cause of fire probably due to short-circuit at the wire-harness.
(Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 36,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 6,572.00)
Nett Liability	<u>S\$ 29,428.00</u> =====

Vehicle Inspected By:



ANG BRYAN TANI
Automotive Assessor / Investigator



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.