

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Tokio Marine Insurance Singapore Ltd  
20 McCallum Street, #09-01 Tokio Marine Centre  
Singapore 069046

**Our File No:** CS/TMI20013274/KDVD3E2

**Date:** 04/12/2020

### REFERENCE

Insured/Claimant:	INVOGUE BIZ PTE LTD	Policy No:	MR003469
Date of Loss:	08/08/2020	Nature of Claim:	OD
		Claim No:	M2003858

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD7579G	Engine No:	1KD2449883
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	KDY2318017429
Reg. Date:	21/04/2015 (Man. Year: 2014)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$36,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

### CONDITION OF TYRES

Front Tyre Size:	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Rear Left Side:	Yokohama 9/9 mm
Front Right Side:	Rear Right Side:	Condor 3/3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11.00</b>	<b>11.00</b>	<b>0.00</b>	<b>0.00</b>
<b>- Excess (\$\$)</b>	3,750.00	3,750.00	0.00	0.00
<b>Nett Amount (\$\$)</b>	<b>-3,739.00</b>	<b>-3,739.00</b>	<b>0.00</b>	<b>0.00</b>

### INSPECTION

Date of Assignment:	02/12/2020 Present Location:	BH Auto Services Pte Ltd (Sin Ming)
Date Inspected:	02/12/2020 Inspected At:	BH Auto Services Pte Ltd (Sin Ming)
		Blk 1 Sin Ming Industrial Estate Sector C,
		#01/111/113/115/117
		Singapore 575636
Estimated Period of Repair:	0.0 days	

**Adjuster:** BRYAN TANI

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :       \$36,000.00  
OMV :               \$30,766.00  
PARF Rebate (1) :     \$0.00  
Quota Premium Paid :   \$15,004.00  
COE Rebate (2) :       \$6,572.00  
Total Rebate (1) + (2) = : \$6,572.00

The total amount incurred will be Market Value \$36,000.00 minus Total Rebate \$6,572.00 = \$29,428.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 Dec 2020)	
<b>Parts:</b>	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD7579G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >