



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

INDIA INSURANCE

Vehicle number	SKH4859R
Make / Model	BMW 320i
Chassis number	WBA3B16080NP42778
Accident date	30/11/20
Reference	2012-02

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	REAR BUMPER <i>Dented</i>	1495.00 ✓	1305.80
1	REAR BUMPER LOWER GARNISH <i>broken</i>	292.00 ✓	
2	REAR BUMPER RETAINER UPPER <i>NH</i>	236.00 X	
2	REAR BUMPER RETAINER LOWER <i>NH</i>	236.00 X	
1	REAR BUMPER INNER GUIDE <i>broken</i>	144.00 ✓	
2	REAR BUMPER BRACKET <i>NH</i>	236.00 X	
2	REAR BUMPER REFLECTOR <i>N/S destroyed o/s NH</i>	208.00 ✓	80.25
1	REAR BUMPER REINFORCEMENT <i>Dented</i>	598.00 ✓	470.25
1	REAR BUMPER TOW COVER <i>distorted / cut</i>	60.00 ✓	
1	BOOTLID <i>St / Dented</i>	1640.00 ✓	1234.80
2	BOOTLID LAMP <i>N/S cut o/s NH</i>	655.50 ✓	327.75
1	BOOTLID WEATHERSTRIP <i>NH</i>	177.60 ✓	
1	BOOTLID LOCK <i>Dented</i>	264.50 ✓	
1	BOOTLID LOCK STRIKER <i>rem</i>	80.50 X	
2	BOOTLID HINGE <i>NH</i>	276.00 X	
2	BOOTLID HINGE COVER <i>NH</i>	96.00 X	
1	BOOTLID EMBLEM - LOGO <i>NH</i>	92.00 ✓	
1	BOOTLID EMBLEM - 320i <i>NH</i>	92.00 ✓	
1	BOOTLID INNER TRIM <i>NH</i>	332.00 X	
4	PDC SENSOR <i>Dented</i>	1150.00 ✓	
1	PDC SENSOR HOLDER <i>NH</i>	102.00 ✓	
1	KEYLESS SENSOR <i>broken</i>	168.00 ✓	
1	NUMBER PLATE GARNISH <i>casing broken</i>	93.60 ✓	25/- NH
2	TAILLAMP <i>mostly broken</i>	966.00 ✓	
2	TAILLAMP BRACKET <i>NH</i>	115.00 X	
1	END PANEL <i>Dented</i>	862.50 ✓	596.60
1	END PANEL TOP GARNISH <i>NH</i>	132.00 X	
1	SPARE TYRE TOP BOARD <i>NH</i>	402.50 X	
1	SPARE TYRE COMPARTMENT <i>Dented</i>	830.00 ✓	
2	REAR FENDER INNER TRIM <i>NH</i>	414.00 X	
2	REAR FENDER <i>N/S repair o/s NH</i>	3910.00 X	
1	REAR EXHAUST <i>St / Dented</i>	1265.00 ✓	
2	REAR EXHAUST MOUNTING <i>1 pc deformed</i>	62.00 ✓	34.50
1	REAR EXHAUST HEATSHIELD <i>St</i>	207.00 ✓	
1	MID PIPE <i>NH</i>	1012.00 X	
		18879.70	
		Less 10%	
		1887.97	
		16991.73	

9860.05

8874.04

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	BOOTLID SPOILER <i>44</i>	550.00 <i>X</i>
1 SET	REAR BUMPER CLIP <i>44</i>	30.00 <i>20/-</i>
1 SET	REAR BUMPER LOWER GARNISH CLIP <i>44</i>	40.00 <i>15/-</i>
1 SET	END PANEL TOP GARNISH CLIP <i>44</i>	40.00 <i>X</i>
1 SET	FENDER INNER TRIM CLIP <i>44</i>	40.00 <i>X</i>
1 SET	BOOTLID INNER TRIM CLIP <i>44</i>	40.00 <i>X</i>
1	REAR NUMBER PLATE <i>34</i> <i>115.00</i>	80.00 <i>X 15/-</i>
1	JOINT SEALANT <i>44</i>	150.00 <i>40/-</i>
Subtotal		970.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		17961.73
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 <i>30/-</i>
2	R & R TRIMS & GARNISHES TO FACILITATE REPAIR	200.00 <i>120/-</i>
3	R & R REAR EXHAUST SILENCER	200.00 <i>80/-</i>
4	R & R REAR PDC SENSOR	150.00 <i>60/-</i>
5	R & R BOOTLID & ATTACHEMENTS TO FACILITATE REPAIR	150.00 <i>60/-</i>
6	PANEL BEATING ON AFFECTED AREAS	1600.00 <i>1000/-</i>
7	SPRAY PAINTING ON AFFECTED AREAS <i>2290.00</i>	1600.00 <i>900/-</i>
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>40/-</i>
Subtotal		4110.00
Grand total		22071.73

03/12/2020 @ 0930hrs

Not Antura

2/5/2021 6 dgs.

Yen

LKK Ando

[Signature]

Check MV

11279.04

L/S 9000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: