LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

LKK Auto Consultants Pte Ltd To: AIG Asia Pacific Insurance Pte. Ltd. From:

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #07-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Mohd Rizal, Nur Mariah Huibrechts Date: 04 Dec 2020

Preliminary Advice

Vehicle No : SKP4011C Accident Date : 27/11/2020 Policy No. : 999995580 Make : TOYOTA CAMRY Assignment Date : 03/12/2020 **Excess** : S\$0.00 : 03/12/2020 Date of Inspection Est. Duration of Repair : 5

: TONG LUCK AUTO PTE LTD (HQ) Inspection At

160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY

SINGAPORE 575722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,099.70
Revised Amount	:S\$	2,504.80
Check Items (Estimated)	:S\$	2,463.40
Total	:S\$	4,968.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	47,552.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,448.00

Remarks

()	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
		have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Vehicle repair on part by part