



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 27/11/2020

ESTIMATE

NO : QUOT202012-000004(00)

DATE : 02/12/2020

POLICY NO : 999995580

VEH REG NO : SKP4011C

MAKE/MODEL : TOYOTA CAMRY 2.5 AUTO

CHASSIS NO : MR053AK5004008066


ENGINE NO : 2ARU158723

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : SKP4011C

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	550.00	550.00 ✓
2 Bonnet <i>chrome</i>	1	115.00	115.00 X
3 Bonnet hinges - LH / RH	2	55.00	110.00 X
4 Bonnet insulator clips <i>(necessary)</i>	15	5.00	75.00 7
5 Support Panel	1	320.00	320.00 7
6 Support Panel top garnish	1	155.00	155.00 7 ✓
7 Support panel top garnish clips <i>(necessary)</i>	8	5.00	40.00 X 205
8 Headlamp assy - LH	1	550.00	550.00 ✓
9 Headlamp bracket - LH	1	58.00	58.00 7
10 Front fender - LH	1	300.00	300.00 X
11 Front bumper	1	320.00	320.00 ✓
12 Front bumper reinforcement	1	170.00	170.00 7 ✓
13 Front bumper bracket - LH	1	68.00	68.00 7
14 Front bumper side retainer - LH	1	48.00	48.00 ✓
15 Front bumper fog lamp - LH	1	135.00	135.00 ✓
16 Front bumper fog lamp chrome - LH	1	65.00	65.00 ✓
17 Front bumper centre grille	1	120.00	120.00 7
18 Front bumper sensor	1	200.00	200.00 7 ✓
19 Front bumper sensor cover	1	28.00	28.00 7 ✓
<i>Front bumper sponge \$80.00</i>			80.00
			3,427.00
		Add 10%	342.70
			3,769.70
LABOUR			
20 To remove and refit air-con condenser, radiator and refill air-con gas	1	150.00	150.00 7
21 To remove and refit front bumper sensor	1	100.00	100.00 50
22 To check and rectify wiring system	1	80.00	80.00 20
23 To panel beat and straighten LH front fender, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,000.00	1,000.00 7
24 To putty and spray paint on affected areas.	1	1,000.00	1,000.00 600
			2,330.00

1170



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 27/11/2020

ESTIMATE

NO : QUOT202012-000004(00)

DATE : 02/12/2020

POLICY NO : 999995580

VEH REG NO : SKP4011C

MAKE/MODEL : TOYOTA CAMRY 2.5 AUTO

CHASSIS NO : MR053AK5004008066

ENGINE NO : 2ARU158723

REG. DATE : 2014

Estimate Repair Cost to Vehicle No : SKP4011C

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		TOTAL	S\$ 6,099.70
		ADD GST @ 7%	426.98
		GRAND TOTAL	<u><u>S\$ 6,526.68</u></u>

SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED TWENTY-SIX AND CENTS SIXTY-EIGHT ONLY

$$\begin{array}{r} \text{B } 3,771.10 \\ \text{XS } 1,500.00 \\ \hline \text{B } 2,271.10 \\ 7\% \quad 158.97 \\ \hline \text{B } 2,430.07 \end{array}$$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE