



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM20013287/Apa3q2 Date: 02/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 4118U	Veh. Inspected	PC 7199J	
Policy No.	P2404131	Coverage (\$)	0.00	
Claim No.	S0M02Y3H	Excess (\$)	0.00	
Assign From		Assign Date	02/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GDH2232000541	Colour	WHITE	
Odometer	174128 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2020	Inspection Date	03/12/2020	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	