

TPAXA Xigo Tong

Page No. 1

GDH 223200541

VEHICLE NO. PC 7199 J

TOYOTA HIACE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bumper <i>rehd</i>		1562.00	479
2	Rear bumper brackets @98.20 RH Dngd		196.40	98.20
1	Rear end panel <i>Rehd</i>		950.00	590
1	Rear end panel top garnish <i>neu</i>		345.00	x
1	Rear RHS taillamp <i>cruld</i>		750.00	355
1	Rear RHS taillamp inner panel <i>Rehd</i>		840.00	570
1	Rear RHS taillamp lower panel <i>Rehd</i>		218.00	145
1	Rear RHS fender <i>Buled</i>		3650.00	2219
1	Rear RHS fender inner garnish <i>cruld</i>		1450.00	745
1	RHS centre panel <i>neu</i>		850.00	x
1	Rear exhaust assy <i>neu</i>		1540.00	x
1	Rear tailgate <i>Rehd</i>	7801.20	2450.00	2040
1	Rear tailgate inner board <i>neu</i>	5850.90	180.00	x
1	Rear tailgate logo <i>neu</i>		125.00	50
1	Rear tailgate HIACE emblem <i>neu</i>		130.00	65
1	Rear tailgate GL emblem <i>neu</i>		90.00	55
1	Rear RHS airduct <i>Rehd</i>		112.00	65
	Tailgate Weatherstripe <i>325</i>			
	<i>Cot</i>			
		less	25%	25%
			15430.40	
			3857.60	
			11572.80	
SPECIAL NETT ITEMS				
1	Rear tailgate A2C sticker <i>neu</i>		60.00	✓
1	Rear tailgate PULL TO OPEN sticker <i>neu</i>		10.00	✓
1	Rear tailgate EMERGENCY DOOR sticker <i>neu</i>		15.00	✓
1	Rear tailgate windscreen sealant <i>neu</i>	205	180.00	60
1	RHS glass sealant <i>neu</i>		280.00	60
	Total Parts		12117.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO. PC 7199 J TOYOTA HIACE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts & components	2200.00 1400	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00 1000.00	
3	To check electrical wiring at damage areas	150.00 30	
4	To remove and refix rear windscreen	180.00 120	
5	To remove and refix RHS glass windows	300.00 150	
6	To remove and replace rear exhaust assy	150.00 X	
7	To remove and refix seat & fittings to commence replace part	300.00 120	2940
5	To perform anti rust treatment on affected areas	350.00 120	
	Labour Total :	5430.00	
	TOTAL (PARTS & LABOUR):	17547.80	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Adrian Lj.
 1/s 03/12/20.
 09 Days.
 Total: 8995.50
 2/s: 7.2K