



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2102382

INV Date 09/04/2021

Reference CC4/LPC20013288/Apa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMT 8655Z
Insured Veh. GBD 2266S
Claim No. 20/20/20/VC05/023951
Policy No. Z20VC05005647
Accident Date 27/11/2020
Inspection Date 03/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20013288/Apa3q2 Date: 09/04/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 2266S	Veh. Inspected	SMT 8655Z	
Policy No.	Z20VC05005647	Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023951	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	02/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180K	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2040452A466885	Colour	BLACK	
Odometer	127148 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2020	Inspection Date	03/12/2020	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 8655Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	1,940.00	1,350.00
2	REAR BUMPER SIDE RETAINERS @\$120.00	N/S DAMAGED	240.00	75.00
1	REAR BUMPER LOWER MOULDING	NOT NECESSARY	550.00	-
1	REAR BUMPER LOWER MOULDING CHROME	CRACKED	180.00	180.00
1	REAR BUMPER INNER FRAME	CRACKED	440.00	215.00
1	REAR BUMPER REINFORCEMENT	DENTED	580.00	580.00
1	REAR END PANEL	DENTED	850.00	850.00
1	REAR END PANEL TOP GARNISH	DEFORMED	250.00	250.00
1	REAR LHS TAILLAMP	CRACKED	980.00	668.00
1	REAR LHS FENDER	BUCKLED	1,850.00	1,850.00
1	REAR EXHAUST ASSY	TO REPAIR SEE LABOUR	2,150.00	-
1	REAR SPARE TYRE TOP COVER	DEFORMED	210.00	210.00
1	REAR BOOTLID	DENTED	2,140.00	1,735.00
1	REAR BOOTLID LOCK ASSY	DAMAGED	340.00	340.00
1	REAR BOOTLID RUBBER MOULDING	CUT	180.00	180.00
1	REAR BOOTLID CHROME	NECESSARY	120.00	120.00
1	REAR BOOTLID C180 EMBLEM	NECESSARY	110.00	110.00
1	REAR BOOTLID KOMPRESSOR EMBLEM	NECESSARY	160.00	160.00
1	REAR BOOTLID LOGO	NECESSARY	130.00	130.00
2	REAR BUMPER CHROM SIDE @\$120.00	NECESSARY	240.00	240.00
	LESS 10% DISCOUNT		-1,364.00	-924.30
			12,276.00	8,318.70
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
2	SET REAR REVERSE SENSOR @\$540.00 (SN)	DAMAGED	1,080.00	500.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
			1,240.00	590.00

Report Ref No. CC4/LPC20013288/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST ASSY .		1,800.00	1,200.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS.		1,400.00	1,000.00
	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION .		150.00	80.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		250.00	100.00
	TO REMOVE AND REFIX REAR WINDSCREEN .		150.00	120.00
	TO REMOVE AND REPLACE REAR EXHAUST ASSY .	NOT NECESSARY	240.00	-
	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATIONS .		300.00	100.00
			4,290.00	2,600.00
	GRAND TOTAL		17,806.00	11,508.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,200.00

Report Ref No. CC4/LPC20013288/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 8655Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 8655Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 8655Z

RE-INSPECTION

