

TP LonPac

Xiao Tony

Page No. 1

WDD2040452A466885

VEHICLE NO. SMT 8655Z

MERCEDES BENZ

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear Bumper <i>Dislud</i>		1940.00	✓ 1350
2	Rear Bumper Side Retainers @\$120 <i>LH 2nd</i>		240.00	75
1	Rear Bumper lower moulding <i>New</i>		550.00	X
1	Rear Bumper lower moulding chrome <i>cruld</i>		180.00	✓
1	Rear Bumper inner frame <i>cruld</i>		440.00	→ 215
1	Rear Bumper reinforcement <i>Dented</i>		580.00	✓
1	Rear end panel <i>Dented</i>		850.00	✓
1	Rear end panel top garnish <i>Delud</i>		250.00	✓
1	Rear LHS taillamp <i>cruld</i>		980.00	668
1	Rear LHS fender <i>Buckled</i>		1850.00	✓
1	Rear exhaust assy <i>Repr</i>		2150.00	X
1	Rear spare tyre top cover <i>Delud</i>		210.00	✓
1	Rear bootlid <i>Dented</i>		2140.00	✓ 1735
1	Rear bootlid lock assy <i>2nd</i>		340.00	✓
1	Rear bootlid rubber moulding <i>ut</i>		180.00	✓
1	Rear bootlid chrome <i>3m</i>		120.00	-
1	Rear bootlid C180 emblem <i>3m</i>		110.00	-
1	Rear bootlid KOMPRESSOR emblem <i>3m</i>		160.00	-
1	Rear bootlid logo <i>3m</i>		130.00	-
	Rear bumper chrome Side @ 120 <i>New</i>		240	✓
		less	10%	10%
			13400.00	
			1340.00	
			12060.00	
<u>SPECIAL NETT ITEMS</u>				
1 set	Rear Bumper Clips <i>3m</i>		60.00	30
2set	Rear reverse sensor @\$540 <i>2nd</i>		1080.00	500
	Rear windscreen Sealant		100	60
	TOTAL PARTS		13200.00	

590

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO. SMT 8655Z MERCEDES BENZ

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1800.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1400.00	1000
3	To remove, refix wiring system at accident damaged areas and check for proper function	150.00	80
4	To perform anti-rust treatment on affected areas	250.00	100
5	To remove and refix rear windscreen	150.00	120
6	To remove and replace rear exhaust assy	240.00	x
7	To clear fault code with diagnostic computer and reset to specifications	300.00	100
	Labour Total :	4290.00	
	TOTAL (PARTS & LABOUR):	17490.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Adrian Lj
h/s 03/12/20
09 Days

total: 11508.70

h/s: 9.2K.