




CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

ESTIMATE		GST Reg No : MR-8500111-7	
Invoice Name & Address		Owner Name & Vehicle Info	
SURESH BABU LOGANATHAN		Cust No/Name	/SURESH BABU LOGANATHAN
481 YIO CHU KANG ROAD		Reg No/Reg Date	SMF8254X*KC17/ 27/11/201
#07-15		Date In/Mileage	/ 0
SINGAPORE 787056		Chassis No	KNAF3416MK5020664
Contact No Mobile: 93392936		Engine No	G4FGJH709779
		Make/Model	KIA/CERATO 1.6 A SR SX G335
		Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	02/12/2020/ 10:25	BLC	442 / CocoLu	25123

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW WINDMIRROR LH, REPAIR FRT BUMPER, FRT FENDER LH, A-PILLAR LH, FRT DOOR LH				400 800.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, WINDMIRROR LH, A-PILLAR LH, FRT DOOR LH				1050 1750.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				X 120.00
M SUNDRY TRANSFER RIM				X 30.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY Sundry				20.00
M MIRROR ASSY-OUTSIDE RR VIEW, LH	1.00	559.00	00.00	559.00
M WHEEL ASSY-ALUMINIUM	1.00	926.00	00.00	926.00

Sten CLKK) 00- Not AuL
Excurs - ?
4/12/20, 12:00 pm
4 days
P/P
By Bel Smy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- ~~Confirmation accepted by~~ "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Authorized signatory and company stamp

	Nett	4,355.00
7% GST on	4355.00	304.85
Total Payable		4,659.85

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.