



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SURESH BABU LOGANATHAN 481 YIO CHU KANG ROAD #07-15 SINGAPORE 787056 Contact No Mobile: 93392936	Cust No/Name /SURESH BABU LOGANATHAN Reg No/Reg Date SMF8254X*KC17/ 27/11/201 Date In/Mileage / 0 Chassis No KNAF3416MK5020664 Engine No G4FGJH709779 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	02/12/2020/ 10:25	BLC	442 / CocoLu	25123

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW WINDMIRROR LH, REPAIR FRT BUMPER, FRT FENDER LH, A-PILLAR LH, FRT DOOR LH				499 800.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, WINDMIRROR LH, x3 A-PILLAR LH, FRT DOOR LH				1050 1750.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				X 120.00
M SUNDRY TRANSFER RIM				X 30.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY Sundry				20.00
M MIRROR ASSY-OUTSIDE RR VIEW, LH / BR	1.00	559.00	00.00	559.00
M WHEEL ASSY-ALUMINIUM X NH	1.00	926.00	00.00	926.00

STEER (LKK) 00- Not AuL
EXCER - ?
4/12/20, 12.00 pm
4 dys
P/P
By Bel spj

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Parts prices are presented without Prejudice* basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

7% GST on Nett 4,355.00
304.85
Total Payable 4,659.85

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.