

ESTIMATE*

SH6349M

02/12/20

IONIQ G2

CHIANG/NTUC

	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR NUMBER PLATE LAMP LH/RH		\$85.30	\$170.60
1	REAR BUMPER BRACKET RH/ LH		\$55.80	\$111.60
			473.25	\$2,087.35
	20.00% DISCOUNTED TOTAL		378.60	\$417.47
				\$1,669.88
1	REAR NUMBER PLATE W/HOLDER		cut	\$55.00
1	REAR REVERSE SENSOR		new	\$180.00
		10.00%		\$211.50
	Labour Charge			
	Panel Beating		320	\$640.00
	Spray Painting Charge		200	\$500.00
	Tuff Kote		new X	\$60.00
	Remove/Refix reverse sensor		30	\$60.00
	TOTAL LABOUR		550	\$1,260.00
	ESTIMATE TOTAL		\$1140.10	\$3,141.38
			02 days #	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Went to take
 Tanphie 97495749
 WP 2/12/20 2/1pm
 02 days
 1/1 Resurvey before paint
 tanphie@lkhands.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: