

MBM WHEELPOWER PTE. LTD.



YOUR REF.: SHC8607L

OUR REF.: SLX3333B

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE: 3/12/2020

FROM: Lee Shirley

FAX: 64525333

CONTACT: 86865188

MAKE & MODEL: TOYOTA ALPHARD 2.5SC 7-SEATER CVT

CHASSIS NO.: AGH300178402

ENGINE NO.: 2ARJ074357

YEAR MADE: 2018

ACCIDENT DATE: 1 December 2020

ESTIMATE FOR VEHICLE NO.: SLX3333B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	FRONT BUMPER		1	\$ 1,800.00
2	FRONT BUMPER SPONGE		1	\$ 120.00
3	FRONT BUMPER RETAINER LH		1	\$ 100.00
4	FRONT BUMPER RETAINER RH		1	\$ 100.00
5	FRONT BUMPER REINFORCEMENT		1	\$ 350.00
6	FRONT BUMPER SENSOR		4	\$ 1,000.00
7	FRONT BUMPER CLIP		10	\$ 50.00
8	FRONT RADIATOR GRILLE		1	\$ 1,800.00
9	FRONT RADIATOR GRILLE LOGO		1	\$ 1,200.00
10	FRONT GRILLE SIDE CHROME LH		1	\$ 195.00
11	FRONT GRILLE SIDE CHROME RH		1	\$ 195.00
12	FRONT TOWING COVER LH		1	\$ 50.00
13	FRONT TOWING COVER RH		1	\$ 50.00
14	FRONT FOG LAMP COVER LH		1	\$ 270.00
15	FRONT FOG LAMP COVER RH		1	\$ 270.00
16	FRONT FOG LAMP LH		1	\$ 220.00
17	FRONT FOG LAMP RH		1	\$ 220.00
18	REAR WINDSCREEN		1	\$ 1,400.00
19	REAR WINDSCREEN MOULDING		1	\$ 100.00
20	TAILGATE		1	\$ 1,800.00
21	TAILGATE WEATHERSTRIP		1	\$ 350.00
22	TAILGATE LICENSE PLATE GARNISH		1	\$ 650.00
23	TAILGATE HINGE LH		1	\$ 75.00
24	TAILGATE HINGE RH		1	\$ 75.00
25	TAILGATE LOCK		1	\$ 720.00
26	TAILGATE TOYOTA LOGO		1	\$ 100.00

27	TAILGATE EMBLEM "ALPHARD"	ACC.	1	\$	105	130.00
28	TAILGATE INNER TRIM	re.	1	\$	/	750.00
29	TAILGATE LAMP LH	X	1	\$		950.00
30	TAILGATE LAMP RH	X	1	\$		950.00
31	TAIL LAMP LH	X	1	\$		650.00
32	TAIL LAMP RH	X	1	\$		650.00
33	REAR BUMPER	re	1	\$	1020.89	1,300.00
34	REAR BUMPER RETAINER LH	re	1	\$	70	100.00
35	REAR BUMPER RETAINER RH	X	1	\$		100.00
36	REAR BUMPER CLIP	ACC	10	\$	/	50.00
37	REAR BUMPER SENSOR	IPC - DM	4	\$	250	1,000.00
38	REAR BUMPER REFLECTOR LH	CRAS	1	\$	86.9	100.00
39	REAR BUMPER REFLECTOR RH	X	1	\$		100.00
40	REAR BUMPER TOWING COVER LH	MTS	1	\$	45	50.00
41	REAR BUMPER TOWING COVER RH	X	1	\$		50.00
42	END PANEL	Buc.	1	\$	/	800.00
43	END PANEL TOP GARNISH	re.	1	\$	/	250.00

TOTAL: \$ 5597.79 21,740.00

LESS 25%: \$ (5,435.00)

PARTS TOTAL: \$ 4198.34 16,305.00

SPECIAL NETT

FRONT & REAR NUMBER PLATE & HOLDER

BODY SEALANT

WINDSCREEN SEALANT

1	\$	40	80.00
1	\$	40	50.00
1	\$	40	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS

TO REMOVE & REPLACE REAR WINDSCREEN

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

TO CHECK & RECONNECT ALL NECESSARY WIRING

TO REMOVE & REFIT ALL SENSOR

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

TO SPRAY PAINT ON THE AFFECTED AREAS

\$	600	1,800.00
\$	120	150.00
\$	60	80.00
\$	30	100.00
\$	40	80.00
\$	NN X	200.00
\$	700	1,600.00

TOTAL: \$ 20,495.00

7% GST: \$ 1,434.65

GRAND TOTAL: \$ 21,929.65

6 Days.

part by part.

before part photos

6mo Qiang - 82880282

07/12/2020.

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SHC8607L

OUR REF.: SLX3333B

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 8/12/2020

FROM: Lee Shirley

FAX: 64525333

CONTACT: 86865188

MAKE & MODEL: TOYOTA ALPHARD 2.5SC 7-SEATER CVT

CHASSIS NO.: AGH300178402

ENGINE NO.: 2ARJ074357

YEAR MADE: 2018

ACCIDENT DATE: 1 December 2020

SUPPLEMENTARY FOR VEHICLE NO.: SLX3333B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR FLOOR UNDERCOVER / <i>BR</i>		1	\$ 157 280.00
2	REAR INNER QUARTER TRIM PANEL LH / <i>RE</i>		1	\$ 500.00
3	REAR TRUNK LUGGAGE HOOK / <i>Yam</i>		1	\$ 20 100.00
4	TAILGATE OPEN/CLOSE SWITCH / <i>Yam</i>		1	\$ 125 180.00
TOTAL:				\$ 802 1,060.00
LESS 20%:				\$ 289 (212.00)
PARTS TOTAL:				\$ 513 848.00

LABOUR

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

TO APPLY ANTI RUST COATING


\$	✓	80.00
\$	✓	50.00
TOTAL:	\$	978.00
7% GST:	\$	68.46
GRAND TOTAL:	\$	1,046.46

~~Lt Bumper Side~~ ✓ *RE*

~~Tailgate Side Garnish~~ ✓ *RE*

Que Qial

08/12/2020.



MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

t 6262 8888 f 6452 5333

COMPANY REG. NO.: 200204110W