

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SHC8607L

OUR REF.: SLX3333B

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE: 3/12/2020

FROM: Lee Shirley

FAX: 64525333

CONTACT: 86865188

MAKE & MODEL: TOYOTA ALPHARD 2.5SC 7-SEATER CVT

CHASSIS NO.: AGH300178402


ENGINE NO.: 2ARJ074357

YEAR MADE: 2018

ACCIDENT DATE: 1 December 2020

ESTIMATE FOR VEHICLE NO.: SLX3333B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	FRONT BUMPER ?		1	\$ 1,800.00
2	FRONT BUMPER SPONGE ?		1	\$ 120.00
3	FRONT BUMPER RETAINER LH ?		1	\$ 100.00
4	FRONT BUMPER RETAINER RH ?		1	\$ 100.00
5	FRONT BUMPER REINFORCEMENT ?		1	\$ 350.00
6	FRONT BUMPER SENSOR X		4	\$ 1,000.00
7	FRONT BUMPER CLIP ?		10	\$ 50.00
8	FRONT RADIATOR GRILLE ?		1	\$ 1,800.00
9	FRONT RADIATOR GRILLE LOGO ?		1	\$ 1,200.00
10	FRONT GRILLE SIDE CHROME LH ?		1	\$ 195.00
11	FRONT GRILLE SIDE CHROME RH ?		1	\$ 195.00
12	FRONT TOWING COVER LH X		1	\$ 50.00
13	FRONT TOWING COVER RH X		1	\$ 50.00
14	FRONT FOG LAMP COVER LH X		1	\$ 270.00
15	FRONT FOG LAMP COVER RH X		1	\$ 270.00
16	FRONT FOG LAMP LH X		1	\$ 220.00
17	FRONT FOG LAMP RH X		1	\$ 220.00
18	REAR WINDSCREEN X		1	\$ 1,400.00
19	REAR WINDSCREEN MOULDING / dec		1	\$ 100.00
20	TAILGATE / blue		1	\$ 1,800.00
21	TAILGATE WEATHERSTRIP / Twi		1	\$ 350.00
22	TAILGATE LICENSE PLATE GARNISH X		1	\$ 650.00
23	TAILGATE HINGE LH X		1	\$ 75.00
24	TAILGATE HINGE RH X		1	\$ 75.00
25	TAILGATE LOCK ?		1	\$ 720.00
26	TAILGATE TOYOTA LOGO X .NN		1	\$ 100.00



27	TAILGATE EMBLEM "ALPHARD" / <i>dec.</i>	1	\$	130.00
28	TAILGATE INNER TRIM / <i>re.</i>	1	\$	750.00
29	TAILGATE LAMP LH ?	1	\$	950.00
30	TAILGATE LAMP RH ?	1	\$	950.00
31	TAIL LAMP LH ?	1	\$	650.00
32	TAIL LAMP RH ?	1	\$	650.00
33	REAR BUMPER / <i>re</i>	1	\$	1,800.00
34	RAER BUMPER RETAINER LH / <i>re</i>	1	\$	100.00
35	RAER BUMPER RETAINER RH / <i>x NN</i>	1	\$	100.00
36	REAR BUMPER CLIP / <i>dec</i>	10	\$	50.00
37	REAR BUMPER SENSOR / <i>IPC - DM</i>	4	\$	1,000.00
38	REAR BUMPER REFLECTOR LH / <i>CEA</i>	1	\$	100.00
39	REAR BUMPER REFLECTOR RH / <i>x NN</i>	1	\$	100.00
40	REAR BUMPER TOWING COVER LH / <i>MTS</i>	1	\$	50.00
41	REAR BUMPER TOWING COVER RH / <i>x NN</i>	1	\$	50.00
42	END PANEL / <i>Buc.</i>	1	\$	800.00
43	END PANEL TOP GARNISH / <i>re.</i>	1	\$	250.00
TOTAL: \$				21,740.00
LESS 25%: \$				(5,435.00)
PARTS TOTAL: \$				16,305.00

<u>SPECIAL NETT</u> / <i>BT</i>				
FRONT & REAR NUMBER PLATE & HOLDER	1	\$	<i>40</i>	80.00
BODY SEALANT / <i>gate.</i>	1	\$		50.00
WINDSCREEN SEALANT	1	\$		50.00

<u>LABOUR</u>				
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	<i>600</i>		1,800.00
TO REMOVE & REPLACE REAR WINDSCREEN	\$	<i>120</i>		150.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	<i>60</i>		80.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>30</i>		100.00
TO REMOVE & REFIT ALL SENSOR	\$	<i>40</i>		80.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	<i>NN X</i>		200.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>700</i>		1,600.00
TOTAL: \$				20,495.00
7% GST: \$				1,434.65
GRAND TOTAL: \$				21,929.65

5 Days.

part by part.

before paint photos

6mo Qiang - 87880282

07/12/2020.