

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5483X****AAD2011-***Not Authorised  
11/11/2020*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**01 DEC 2020****SHC5483X**

VF1ABL15AUC277525

RENAULT

LATITUDE

*27.11.2020**Alh*

11/07/2014

**PART**

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 FENDER PANEL REAR RH
- 1 FENDER BRACKET LOWER RH
- 1 TAILLAMP *RH*
- 1 WHEELARCH REAR RH

**LIST**

\$	<i>Bumper</i>	561.70	
\$	<i>Rh</i>	411.90	
\$	<i>Rh</i>	547.80	
\$	<i>Rh</i>	114.50	
\$	<i>Rh</i>	114.50	
\$	<i>Rh</i>	1,933.20	
\$	<i>Rh</i>	11.80	
\$	<i>Rh</i>	401.40	
\$	<i>Rh</i>	275.40	

<b>TOTAL</b>	\$	<b>4,096.80</b>
<b>10%</b>	\$	<b>409.68</b>
	\$	<b>3,687.12</b>

**Special Nett**

- 1SET FENDER SCREW
- 1SET CLIP, FRONT FENDER LINER
- 1 BUMPER CLIP FRT
- 1 BUMPER RETAINER CLIP FRT
- 1 WHEELARCH CLIP FRT
- 1 DOOR FINISHER CLIP KIT FRT RH
- 1 DOOR MOULDING CLIP L70Y
- 1 DOOR MOULDING SCREW L70Y
- 1 DOOR CASING CLIP
- 1 REAR DOOR STICKER '6555-3333'
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	<i>na</i>	60.00	<i>X</i>
\$	<i>na</i>	65.00	<i>X</i>
\$	<i>na</i>	90.00	<i>665n</i>
\$	<i>na</i>	75.00	
\$	<i>na</i>	75.00	
\$	<i>na</i>	90.00	
\$	<i>na</i>	80.00	
\$	<i>na</i>	65.00	
\$	<i>na</i>	85.00	
\$	<i>na</i>	100.00	
\$	<i>na</i>	150.00	
\$	<i>na</i>	200.00	
\$	<i>na</i>	130.00	

<b>TOTAL</b>	\$	<b>365.00</b>
--------------	----	---------------

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5483X****AAD2011-****TOTAL PARTS \$ 4,052.12****LABOUR**

Towing fees	\$	<i>na</i>	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i>	300.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i>	220.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>4</i>	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.	\$	<i>4</i>	380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		1,400.00	<i>2201</i>
To rust-proofing and apply undercoat of the affected areas.	\$	<i>4</i>	240.00	X
Putty and spray painting of the affected portion.	\$		1,400.00	<i>2201</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i>	170.00	X
To Check Electrical Lighting Concerned.	\$	<i>4</i>	170.00	X

**TOTAL \$ 4,750.00****Over All Total \$ 8,802.12**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No interest in the vehicle is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**For Official Use**

Acknowledged by Repairer

Signature:

Date:

**LUMP SUM (REPAIR DAY)****20 DAYS***1 1/2 days*